

JTB00577NAS1

TECHNICAL BULLETIN

16 NOV 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION**SECTION:**

205-04: Front Drive Halfshafts

SUBJECT/CONCERN:

Rubbing Noise From Front of Vehicle at Low Speeds

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
F-PACE (X761)	2017-2018	045068-099996	Solihull

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
F-PACE (X761)	2017	488002-499998	Solihull
F-PACE (X761)	2017-2018	880002-899997	Solihull
F-PACE (X761)	2018 Onwards	240000 Onwards	Solihull

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

A rubbing noise from the front of the vehicle at low speeds may be evident.

CAUSE:

This may be caused by a harmonic resonance from the front right halfshaft support bracket.

ACTION:

Should a customer express this concern, follow the Workshop Procedure below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY
T4A29627	Halfshaft support bracket	1
T4A12521	Circlip	1
XR848057	Nut	1
T2H6322	Nut	1
T2H17786	Bolt	1
T2H3159	Nut	1

PART NUMBER	DESCRIPTION	QUANTITY
C2Z2224	Nut	1
T4N8037	Nut	1
T4A11659	Bolt	2
T2H13851	Drain Plug	1
T2H13852	Fill Plug	1
C2P25272	Differential Oil	1
C2P12731	Hub Nut	1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:
NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Halfshaft support bracket - Renew	47.10.37	1.4	12	T4A3241

NOTE:

Normal Warranty procedures apply.

WORKSHOP PROCEDURE:

- 1 Renew the halfshaft support bracket (see TOPIx Workshop Manual section 205-04: Front Drive Halfshafts - Removal and Installation - Halfshaft Support Bracket).