



# Technical Journal

TITLE:

**Sensus downloading problems. IAM 2.1 system**REF NO:  
**TJ 26525.3.0**ISSUING DEPARTMENT:  
**Technical Service**CAR MARKET:  
**United States and Canada**PARTNER:  
**3 US 7510 Volvo Car USA**ISSUE DATE:  
**2017-06-23**STATUS DATE:  
**2017-06-27**FUNC GROUP:  
**3900**FUNC DESC:  
**Media, navigation and  
communication**

Page 1 of 3

**“Right first time in Time”**

## Attachment

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124							2012-2015		0151101-0184738	201120-201419
134							2011-2015		0000001-0318592	201020-201419
136							2012-2015		0118101-0202917	201120-201419
138							2014-2015		0000001-0009539	201345-201419
155							2014-2015		0000001-0214070	201035-201419
156							2011-2015		0172111-0677509	201046-201419

## CSC Customer Symptom Codes

Code	Description
FC	Audio other/Other audio problems
EO	Navigation/Does not work
2V	Technician information/Software/Vehicle communication/Not for warranty use
3L	Technician information/Repair information/Not for warranty use

## VST Operation Number

VST Operation Number	Description
36004-2	Software Control Module Downloading
36002-3	Software Control Module Downloading (2:nd)



## DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
CEM	U015600	Intermittent
DIM	U015600	Intermittent
CCM	U015600	Intermittent

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

## Text

### DESCRIPTION:

**\*This TJ is re-written in its entirety**

ICM - Infotainment Control Module

IAM - Integrated Audio Module

VIDA - Vehicle Information and Diagnostics for Aftersales

SP - Software Product

ECU - Electronic Control Unit\*

If you encounter problems with loading software to the IAM or ICM on Sensus (IAM2.1) vehicles (listed above), please follow the instructions under Service.

Examples of issues you may encounter:

- Error messages in VIDA:  
“A fault occurred during download due to the PIN for opening the ECU being incorrect. The error occurred while trying to download to ICM (61)”
- “The node is not able to receive software package with the speed dice is set for.”
- The download may start and then be interrupted and fail after a few minutes. The ICM may show as Not responding in the Advanced Test window in VIDA after a failed software download attempt.

\*For the purposes of this document, “ECU” refers to an Electronic Control Unit which is identified in the fault text.

### SERVICE:

Download ICM recovery software in 3 steps:

#### S60/S60I/V60/XC60:

ICM RECOVERY STEP 1: SP 32218340

ICM RECOVERY STEP 2: SP 32218341

ICM RECOVERY STEP 3: SP 32218342



### XC70/S80:

ICM RECOVERY STEP 1: SP 32218346

ICM RECOVERY STEP 2: SP 32218347

ICM RECOVERY STEP 3: SP 32218348

Once the recovery is complete, proceed with the IAM or ICM software upgrade or reload that was originally being attempted.

**IMPORTANT NOTE:** These software products should **ONLY** be used if you encounter a failure during the software download process. Using them for any other reason will cause other faults.

**WARRANTY ADMINISTRATOR:** Failed software downloads and related fault tracing can be claimed using **PARTS WARRANTY**.

### **VEHICLE REPORT:**

Please submit a Technical Helpdesk Vehicle Report in TIE if you still can not download software after performing the procedure above. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3972.