

## **Technical Information**

Service

23/14 ENU 2480

2

Eliminating Symptoms - Engine: Replacing Intake Manifold Pressure Sensor (Vehicle jerking while driving/SY2314)

Eliminating symptoms - Engine: Replacing intake manifold pressure sensor (Vehicle jerking while driving)

Vehicle Type: 918 Spyder

Model Year: 2015

Subject: Intake manifold pressure sensor

Symptom: Vehicle jerking while driving using the combustion engine.

Cause: If the vehicle is driven continuously in the high-load range (e.g. race track driving), vibrations can damage

the connector contacts on the intake manifold pressure sensors.

Remedial Action:

In the event of a complaint and if fault codes are entered (see overview below), check which type is installed on the vehicle - with or without adapter intermediate piece on the intake manifold pressure sensor connector.

⇒ Depending on which type is installed:

- an existing adapter intermediate piece must be replaced by a new adapter cable or
- the adapter intermediate piece must be removed and the connector on the engine wire harness must be replaced.

Date of Introduction:

Modified intake manifold pressure sensors have been installed during production since the end of April 2014.

# Overview of fault codes

Fault code:	Cylinder bank:	Component:	Fault:
P010600	⇒ Bank 1	Intake manifold pressure sensor	Signal implausible
P010700	⇒ Bank 1	Intake manifold pressure sensor	Short circuit to ground
P010800	⇒ Bank 1	Intake manifold pressure sensor	Short circuit to B+
P2A0B00	⇒ Bank 2	Intake manifold	Signal implausible

pressure sensor

Dec 7, 2017 Page 1 of 4 2

### Service

2480 ENU 23/14

**Technical Information** 

-			
P024100	⇒ Bank 2	Intake manifold pressure sensor	Short circuit to ground
⇒ FC is replaced by:			
P2A0C00	⇒ Bank 2	Intake manifold pressure sensor	Short circuit to ground
P024200	⇒ Bank 2	Intake manifold pressure sensor	Short circuit to B+
$\Rightarrow$ FC is replaced by:			
P2A0D00	⇒ Bank 2	Intake manifold pressure sensor	Short circuit to B+

Parts Info: Variant a) 918.607.105.00 – NEW – ⇒ Adapter with cable (2 ea. required)

Variant b) 918.607.913.00 - NEW - ⇒ Engine wire harness connector (set, 2 ea. required;

consisting of: connectors, contacts and single-wire seal)

**991.606.180.00 – NEW –**  $\Rightarrow$  Intake manifold pressure sensor

## Work Procedure:

#### Replace intake manifold pressure sensor:

- 1 Remove exhaust system, see Workshop Manual ⇒ Workshop Manual '260119 Removing and installing exhaust system', section on "Preliminary work" and "Removing exhaust system".
- 2 Evaluate existing type:

23/14 ENU 2480




Figure 1

- 2.1 If the **adapter intermediate piece is already fitted** between the engine wire harness and intake manifold pressure sensor connector (⇒ *Figure 1* **Left**-)
  - $\Rightarrow$  Replace the **existing adapter intermediate pieces with the adapter cables** (variant a Part No.: 918.607.105.00 Adapter with cable 2 required) **and replace the intake manifold pressure sensors**.

Continue with Step ⇒

- 2.2 If there is **no adapter intermediate piece** between the engine wire harness and intake manifold pressure sensor connector (⇒ *Figure 1* **Right**-)

  The engine wire harness connector (⇒ *Figure 1* **Posi. 1**-) is secured directly to the intake manifold pressure sensor connector.
  - ⇒ The engine wire harness connector must be reworked:

#### **Technical Information**

- 2.2.1 Disconnect engine wire harness connector from the cable (⇒ Figure 1 Use wire cutters Pos. 1-) and crimp the new connector with new contacts and single-wire seals (variant b Part No. of set: 918.607.913.00 2 required) to the engine wire harness.
- 2.2.2 Repeat Step  $\Rightarrow$  2.2.1 on the other cylinder bank.
- 3 Install exhaust system, see Workshop Manual ⇒ Workshop Manual '260119 Removing and installing exhaust system', section on "Installing exhaust system" and "Subsequent work".

End of action required.

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
24801951	Removing and installing intake manifold pressure sensor	
24801952	Removing and installing intake manifold pressure sensor	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	24800	Intake manifold pressure sensor
Damage type (SA4) 9735		Repair in accordance with PAG instructions

References: ⇒ Workshop Manual '260119 Removing and installing exhaust system'

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safety. If a particular condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your authorized Porsche Dealer for the latest information about whether a particular technical bulletin applies to your vehicle. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify the current and correct part numbers. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.