



Technical Service Bulletin

72 Seat belt positioner intermittently inoperative

72 17 18 2048311/1 July 18, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
S5 Cabriolet	2017	All	With S Sport Seats
S5 Cabriolet	2018	000001 - 003234	With S Sport Seats

Condition

On S5 Cabriolet equipped with S Sport Seats (PR Q4Q) the customer may report that the seatbelt positioner is intermittently inoperative.



Note:

Only vehicles with S Sport Seats with PR code Q4Q are affected. The seatbelts function normally, only the seatbelt positioner is an issue. No DTC's are stored.



Figure 1. S Sport Seats, PR Q4Q in the S5 Cabriolet.

Technical Background

Depending on the seat version with which the vehicle comes equipped, the seat could be adjusted to a position where the seatbelt positioner arm could make contact with the seatback e.g. seat adjusted fully upward and seatback tilted forward. The S5 Cabriolet equipped with S Sport seats PR number Q4Q are currently programmed to not activate the seatbelt positioner when the seat was adjusted in this way. The S5 Cabriolet equipped with S Sport seats PR number Q4Q are not at risk for contact between the seat and the seatbelt positioner.

Production Solution

A software change has been implemented in production that changes the behavior of the seatbelt positioner.



Technical Service Bulletin

Service

On the S5 Cabriolet an update to both seat control units with SVM code 36A002 is required. No further work is necessary. The seatbelt positioner will operate in all seat positions.


SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update both seat control units using the SVM action code as listed in the table below, if necessary:

Model(s)	Engine and/or Transmission	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Code Input
S5 Cabriolet (Equipped with PR code Q4Q S Sport Seats)	N/A	4M0 959 760*	0031	4M0 959 760*	0031	36A002

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	6438		
Damage Code:	0040		
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 70 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		



Technical Service Bulletin

Claim Comment:	As per TSB #2048311/1
-----------------------	-----------------------

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

- TSB 2011732 00 *Software Version Management (SVM), operating instructions*.

All part and service references provided in this TSB (2048311) are subject to change and/or removal. Always check with your Parts Dept. and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.