

Technical Service Bulletin

00 DTC U110500 (Transport mode active) cannot be cleared

00 17 98 2042954/4 July 31, 2017. Supersedes Technical Service Bulletin Group 00 number 17-86 dated March 15, 2017 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, and Q5	2017 - 2018	All	Not Applicable
Q7	2017	All	Not Applicable

Condition

REVISION HISTORY				
Revision	Date	Purpose		
4	-	Revised header data (Added models)		
3	03/15/2017	Revised Service (Added information)		
2	01/11/2016	Revised Condition (Added Tip)		
		Revised Technical Background (Completely revised)		
		Revised Service (Added information about ignition and engine status)		

• The vehicle cannot be taken out of transport mode.

The following DTC is found in the ABS control module, J104 (address word 0003):

• DTC U110500 (Transport mode active)

Tip: It is not necessary to contact TAC for this issue.

Technical Background

The ABS module is causing the DTC.

If the vehicle is taken out of transport mode while the engine is running, the ABS module will remain stuck in transport mode and cannot be cleared.

Page 1 of 3

^{© 2017} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Production Solution

Not applicable.

Service

Only take the vehicle out of transport mode with the <u>ignition on</u> and the <u>engine off</u>. If this does not work, proceed as follows:

- 1. With the ignition off, disconnect the ABS module, then reconnect it.
- 2. Cycle the ignition on, then reactivate transport mode through the GFF test plan.
- 3. Perform the GFF transport mode test plan again and deactivate transport mode.
- 4. Clear all DTCs and check to see that the issue has been resolved.

If any of the DTCs will not clear, perform the following procedure:

- 1. Fresh reboot of ODIS.
- 2. Hardwire or Bluetooth does not matter, re-run fresh ODIS session.
- 3. Cycle the key one time (key OFF key ON).
- 4. Right click 03 (Brake control module).
- 5. Select Guided Functions.
- 6. Select Check and erase DTC memory.
- 7. Erase DTC in the test plan.
- 8. Read all module DTC to assure faults are cleared.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.


Additional Information

All parts and service references provided in this TSB (2042954) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in

^{© 2017} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2017 Audi of America, Inc.

Page 3 of 3

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.