

| Model | Year | Eng. Code | Trans. Code | VIN Range From | VIN Range To |
|-------|-----------|-----------|-------------|----------------|--------------|
| Jetta | 2016-2017 | 1.4T | All | AJ_GM000001 | AJ_HM272378 |
| | | (CZTA) | | | |

Condition

01 17 03 February 21, 2017 **2045384** Supersedes Technical Bulletin V011702 dated February 21, 2017 to adjust road test time units in warranty table.

Update Programming, DTC P3081 Stored in ECM Fault Memory



This software update also proactively includes updates for fault code(s) P0556, P0456 and P0300 - P0304 found in the ECM - *J623* -.

| DTC | Description | | |
|-------|----------------------------|--|--|
| P3081 | Engine temperature too low | | |

Technical Background

Current Engine Control Module (ECM) software for cooling system monitoring not sufficient.

Production Solution

Improved Engine Control Module software in production CW41/16 VIN 3VWB67AJ7HM272378.



Service

Update Programming Procedure:



To Update-Programming using SVM, **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim.

Note:

Prior to launching the ODIS service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Special Tools and Equipment - Service Information Circular # VVT-12-02. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure.

When using a VAS 6150/X or 6160/X tester in conjunction with a VAS 5054A wireless transmitter head for a flash procedure, please connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.

<u>Critical Warning</u>: The Midtronics Battery Charger <u>must</u> be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process, and should monitor the voltage for the duration of the update.



WARNING:

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades.

Keep hands and all objects away from Radiator Fan(s) during Update Process!



Update the Engine Control Module using the SVM Unit code as listed in the table below:

| Model | Engine | Old Software Part No. | Old Software Version | New Software Part No. | New Software Version (or higher) | SVM Unit Code |
|-------|--------|--------------------------|-------------------------|--------------------------|-------------------------------------------|------------------|
| Jetta | 1.4T | 04E906023AK | 3532 | 04E906023AK | 3670 | 3D63 |
| | (CZTA) | | 2849 | | | |
| Jetta | 1.4T | 04E906023AL | 3531 | 04E906023AL | 3669 | |
| | (CZTA) | | 2850 | | | |
| Jetta | 1.4T | 04E906023AP | 2953 | 04E906023AK | 3670 | |
| | (CZTA) | | 2721 | | | |
| Jetta | 1.4T | 04E906023AQ | 2954 | 04E906023AL | 3669 | |
| | (CZTA) | | 2722 | | | |
| Jetta | 1.4T | 04E906023N | 2529 | 04E906023AK | 3670 | |
| | (CZTA) | | 1599 | | | |
| | | | 0731 | | | |
| Jetta | 1.4T | 04E906023P | 2528 | 04E906023AL | 3669 | |
| | (CZTA) | | 1571 | | | |
| | | | 1093 | | | |
| | | | 0732 | | | |

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.



The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

Ensure attached ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.



Warranty

| Model(s) | Year(s) | | Eng. Code(s) | Trans. Code(s) | VIN | VIN Range F | | VIN Range To |
|----------------------------------------|-----------|-------------------------------|----------------------------------------|-----------------------|------------------------------------------------|-------------|--------|--------------|
| Jetta | 2016-2017 | | 1.4L | AII | A | AJ_GM0000 | | AJ_HM272378 |
| | | | (CZTA) | | | | | |
| | | | SAGA | Coding | | | | |
| Claim Type: | | Use app | licable Claim Type | 1) | | | | |
| Service Number: | | Damage Code | нѕт | | Damage Location (Depends on Service No.) | | | |
| 2470 | | 0039 | | | Use applicable when indicated in Elsa (L/R) | | | |
| Parts Manufacturer | | | Jetta | | 3ME ²⁾ | | | |
| Labor Operation 3): Charge Battery | | | | 27068950 = 10 TU | | | | |
| Labor Operation 3): Update Programming | | | Included in GFF Time expenditure below | | | | | |
| Causal: Select Labor Operation | | | | 01500000 | | | | |
| | | | Diagnost | ic Time ⁴⁾ | | | | |
| GFF Time expenditure | | | 01500000 = 50 TU max | | YES | | | |
| Road Test | | 01210004 = <mark>10 TU</mark> | | YES | | | | |
| Technical Diagnosis | | 01320000 = 00 TU max. | | | NO | | | |
| 01-10 | Innut "A | T | hnical Bulletin 204 | 1520 4" in a am | | toootion | of Mor | rents Claim |

²⁾ Code per warranty vendor code policy.

³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.

⁴⁾ Documentation required per Warranty Policies and Procedures Manual.



Required Parts and Tools

No Special Parts required.

| Tool Description | Tool No: | |
|-----------------------------------|------------------------------------------|--|
| Midtronics Battery Tester/Charger | InCharge 940 (INC-940) | |
| | or | |
| | GRX3000VAS | |
| VAS Diagnostic Tool | VAS 6150/X & VAS 6160/X and | |
| | ODIS Service with current online updates | |

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

| Document Control Revision Table | | | | | | |
|---------------------------------|----------------|----------------|--------------------------------------------------|--|--|--|
| Instance Number | Published Date | Version Number | Reason For Update | | | |
| 2045384/4 | 2/21/17 | V011703 | To adjust road test time units in warranty table | | | |
| 2045384/1 | 11/1/16 | V011619 | Original publication. | | | |



OWNER INFORMATION ABOUT CONTROL MODULE TUNING* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

| *) "TUNING" is described as the addition of or modification of any cor Volkswagen vehicle to perform outside the normal parameters and sp Volkswagen Group of America / Volkswagen Group Canada. | • |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|
| | |
| Date: | |
| Dealer Number: | |
| Vehicle Identification Number: | |
| Repair Order Number: | |
| | Dealer stamp |
| I, owner or driver of the above identified | · |
| "Tuning" as described above (especially power increasing modifiperformed on my vehicle. | |
| Tuning" as described above has been performed on my vehicle and were modified or installed: | the following components |
| TUNING was performed by (Please provide Company name and telepho to contact them): | ne number, if you wish us |
| I understand that if my Control Module is determined to have been tuned the tuning of the Control Module (including adverse emissions conseque by VWGoA / VGC warranties. | |
| I am permitting an authorized Volkswagen Dealer to reflash (update) my doing so, I understand that this process will automatically overwrite (d delete any tuning program that was previously installed on the Control M vehicle. | estroy) and permanently |
| By signing below, I fully acknowledge and understand that the tuning pro and VWGoA / VGC, will not be liable in any way for the loss of tuning da | |
| Signature | of Customer |