

#### 01 Engine sporadically difficult to start - 4.0TFSI

01 17 06 2046724/2 March 28, 2017. Supersedes Technical Service Bulletin Group 21 number 17-25 dated March 2, 2017 for reasons listed below.

| Model(s)   | Year        | VIN Range | Vehicle-Specific Equipment |
|------------|-------------|-----------|----------------------------|
| S6         | 2015        | All       | 4.0 TFSI                   |
| RS 7       | 2014 - 2017 | All       | 4.0 TFSI                   |
| S8         | 2013 - 2016 | All       | 4.0 TFSI                   |
| A8, S7     | 2013 - 2017 | All       | 4.0 TFSI                   |
| RS 7+, S8+ | 2016 - 2017 | All       | 4.0 TFSI                   |

### **Condition**

| REVISION HISTORY      |            |  |  |  |
|-----------------------|------------|--|--|--|
| Revision Date Purpose |            |  |  |  |
| 2                     | -          | Revised Customer Statement and Service (Updated SVM Table) |  |  |
| 1                     | 03/02/2017 | Initial publication  |  |  |

#### **Customer statement:**

- The engine sporadically does not start after reaching operating temperature and being parked for longer stationary periods (engine not completely cooled down). However, the starter motor will turn over normally.
- The engine sporadically does not start or only after long cranking period then runs rough for a few seconds (starter motor turns normal).

#### Workshop findings:

Usually no DTC event entries in engine control module (ECM), J623 (address word 0001).

Or

• Sometimes DTC event entries about fuel metering system "System too rich" in engine control module (ECM), J623 (address word 0001).



### **Technical Background**

Deviation in fuel-air mixture at engine start.

### **Production Solution**

Not applicable.

### **Service**

#### Perform the following checks:

- 1. Read the DTC memory of the ECM.
- Read/assess the measured value with the ODIS measured value identifier IDE09529 "Fuel mass flow fumigation from engine oil". Warm up the engine at idle speed and observe the above measured value together with the engine oil temperature. The evaporation process of fuel in the engine oil starts at about 122°F engine oil temperature.
  - a. If the value of the fuel mass flow is at least intermittently above 75 mg/s, this clearly points to a high fuel share in the engine oil (over 0.5 l). In this case, the condition is caused by an extreme short distance operation profile of the customer. We recommend to change the engine oil and to explain the background to the customer. Update the ECM with SVM code 01A225.
  - b. If the limit of 75 mg/s is not exceeded and the condition cannot be reproduced, the driving profile of the customer before the workshop visit may have completely consumed the fuel in the engine oil. In this case, we also recommend to enquire about the driving profile of the customer for a possible explanation. In this case, also update the ECM with SVM code 01A225. An oil change is not necessary.

#### In addition check the following fuel pressure values:

- 1. Check the holding pressure of the high and of the low pressure fuel pump (fuel pump for pre-supply G6) at room temperature (about 64-68°F):
  - Warm up the engine to an oil temperature of at least 176°F and read the following measured values:
    - IDE00186 low fuel pressure, actual value
    - IDE00188 high fuel pressure, actual value
    - IDE06212 fuel pressure high-pressure accumulator 2
  - Observe the development of the high fuel pressure after switching off the engine (required pressure development: gradual rise to about 80 bar in 10 minutes). If the pressure development is different, the



cause of the condition can be a leaking high pressure fuel injector. In this case, borescope the combustion chamber to determine if there is a leak from one of the high pressure fuel injectors.

Also, observe the pressure build-up of the low fuel pressure after switching off the engine. In the first five
minutes the low pressure must rise above 6 bar and the pressure must be held for another 10 minutes. If
the low fuel pressure was built up correctly but drops by more than 1.5 bar in the first 15 minutes, it can be
assumed that at least one of the high-pressure fuel pumps is leaking. In this case replace both highpressure fuel pumps and change the engine oil.

#### **SVM Update Instructions**

- 1. Follow all instructions in TSB 2011732: 00 Software Version Management (SVM), operating instructions.
- 2. Update the ECM, J623 (address word 0001) using the SVM action code as listed in the table below if necessary:

| Model         | Engine | Old Software<br>Part Number | Old Software<br>Version | New Software<br>Part Number | New<br>Software<br>Version<br>(or higher) | SVM Code<br>Input |
|---------------|--------|-----------------------------|-------------------------|-----------------------------|---|-------------------|
| S6/S7 MY13    | CEUC   | 4G0906014                   | 0011                    | 4G0906014                   | 0012                                      | 01A225            |
| S6/S7 MY13    | CEUC   | 4G0906014A                  | 0007                    | 4G0906014A                  | 0008                                      | 01A225            |
| S6/S7 MY13    | CEUC   | 4G0906014B                  | 0008                    | 4G0906014B                  | 0009                                      | 01A225            |
| S6/S7 MY14    | CEUC   | 4G0906014E                  | 0005                    | 4G0906014E                  | 0006                                      | 01A225            |
| S6/S7 MY15    | CEUC   | 4G0906014E                  | 0005                    | 4G0906014E                  | 0006                                      | 01A225            |
| S6/S7 MY16    | CTGE   | 4G0906014C                  | 0005                    | 4G0906014C                  | 0006                                      | 01A225            |
| S6/S7 MY16-17 | CTGE   | 4G0906014D                  | 0001                    | 4G0906014D                  | 0002                                      | 01A225            |
| RS 7 MY14     | CRDB   | 4G0906560A                  | 0005                    | 4G0906560A                  | 0006                                      | 01A225            |
| RS 7 MY14     | CRDB   | 4G0906560                   | 0011                    | 4G0906560                   | 0012                                      | 01A225            |
| RS 7 MY14     | CRDB   | 4G0906560B                  | 0007                    | 4G0906560B                  | 0008                                      | 01A225            |
| RS 7 MY15-16  | CWUB   | 4G0906560D                  | 0001                    | 4G0906560G                  | 0002                                      | 01A225            |
| RS 7 MY15-16  | CWUB   | 4G0906560F                  | 0002                    | 4G0906560F                  | 0003                                      | 01A225            |



|                             |      |            |      | T          |      |        |
|-----------------------------|------|------------|------|------------|------|--------|
| RS 7 MY17                   | CWUB | 4G0906560G | 0001 | 4G0906560G | 0002 | 01A225 |
| RS 7 MY16-17<br>Performance | CWUC | 4G0906560G | 0001 | 4G0906560G | 0002 | 01A225 |
| A8 4.0TFSI<br>MY13-14       | CEUA | 4H0906014  | 0007 | 4H0906014  | 0008 | 01A225 |
| A8 4.0TFSI<br>MY13-14       | CEUA | 4H0906014A | 0005 | 4H0906014A | 0006 | 01A225 |
| A8 4.0TFSI<br>MY13-14       | CEUA | 4H0906014B | 0004 | 4H0906014L | 0005 | 01A225 |
| A8 4.0TFSI<br>MY13-14       | CEUA | 4H0906014C | 0004 | 4H0906014C | 0005 | 01A225 |
| A8 4.0TFSI<br>MY13-14       | CEUA | 4H0906014D | 0004 | 4H0906014D | 0005 | 01A225 |
| A8 4.0TFSI<br>MY13-14       | CEUA | 4H0906014H | 0005 | 4H0906014H | 0006 | 01A225 |
| A8 4.0TFSI<br>MY13-14       | CEUA | 4H0906014L | 0004 | 4H0906014L | 0005 | 01A225 |
| A8 4.0TFSI MY15             | CTGA | 4H0906014G | 0007 | 4H0906014G | 0008 | 01A225 |
| A8 4.0TFSI MY15             | CTGA | 4H0906014J | 0005 | 4H0906014J | 0006 | 01A225 |
| A8 4.0TFSI MY15             | CTGA | 4H0906014K | 0004 | 4H0906014K | 0005 | 01A225 |
| A8 Sport MY16               | CTGF | 4H0906014N | 0001 | 4H0906014N | 0002 | 01A225 |
| S8 MY13                     | CGTA | 4H0907557  | 0009 | 4H0907557  | 0010 | 01A225 |
| S8 MY13                     | CGTA | 4H0907557A | 0005 | 4H0907557A | 0006 | 01A225 |
| S8 MY13                     | CGTA | 4H0907557B | 0004 | 4H0907557E | 0004 | 01A225 |
| S8 MY14                     | CTFA | 4H0907557E | 0003 | 4H0907557E | 0004 | 01A225 |
| S8 MY15-16                  | CTFA | 4H0907557C | 0005 | 4H0907557C | 0006 | 01A225 |



| S8 MY15-16   | CTFA | 4H0907557D | 0005 | 4H0907557D | 0006 | 01A225 |
|--------------|------|------------|------|------------|------|--------|
| S8 MY15-16   | CTFA | 4H0907557F | 0002 | 4H0907557F | 0003 | 01A225 |
| S8 Plus MY16 | DDTA | 4H0907557G | 0003 | 4H0907557G | 0004 | 01A225 |
| S8 Plus MY16 | DDTA | 4H0907557H | 0001 | 4H0907557H | 0002 | 01A225 |

<sup>3.</sup> After the SVM update, cycle the ignition.

### **Warranty**

| Claim Type:       | • 110 up to 48 Months/50,000 Miles.  |           |   |  |  |  |
|-------------------|--|-----------|---|--|--|--|
|                   | • 1E1 up to 8 Years/80,000 Miles.  |           |   |  |  |  |
|                   | G10 for CPO Covered Vehicles – Verify Owner.   |           |   |  |  |  |
|                   | If vehicle is outside any warranty, this Technical Service Bulletin is informational only. |           |   |  |  |  |
| Service Number:   | 2470   |           |   |  |  |  |
| Damage Code:      | 0039   |           |   |  |  |  |
| Labor Operations: | Check software level in ECM (with no update needed)  | 2470 0199 | 10 TU   |  |  |  |
| Diagnostic Time:  | GFF - Checking and clearing fault codes included in existing labor operations              | 0150 0000 | Time stated<br>on diagnostic<br>protocol (Max<br>50 TU) |  |  |  |
|                   | Road test prior to service procedure   | 0121 0002 | 10 TU   |  |  |  |
|                   | Road test after service procedure  | 0121 0004 | 10 TU   |  |  |  |
|                   | Technical diagnosis at dealer's discretion   |           |   |  |  |  |
|                   | (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)             |           |   |  |  |  |
| Claim Comment:    | As per TSB #2046724/2  |           |   |  |  |  |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



### **Additional Information**

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

• TSB 2011732 00 Software Version Management (SVM), operating instructions.

All parts and service references provided in this TSB (2046724) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.