

Technical Service Bulletin

19 Coolant temperature sporadically too high, C7 V6

19 17 83 2030623/2 March 21, 2017. Supersedes Technical Service Bulletin Group 19 number 12-33 dated September 7, 2012 for reasons listed below.

Model(s)	s) Year VIN Range		Vehicle-Specific Equipment	
A6/A7 V6	2012	000001 – 079045	CGXB Engine Code	

Condition

REVISION HISTO	EVISION HISTORY						
Revision	Date	Purpose					
2	-	Revised Required Parts and Tools (Added Reservoir)					
1	09/07/2012	Initial publication					

- Coolant temperature too high (thermostat function has been verified).
- Coolant warning on.

Technical Background

A small non-return valve is fitted in the coolant hose (**4G0 121 081 AH**) to the reservoir.

The flow must *only* go towards the reservoir and be blocked to the engine.



Page 1 of 3

^{© 2017} Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Figure 1. Small non-return valve fitted with coolant hose.

Production Solution

Optimized process at the supplier from VIN number _FC1CN079045 on.

Coolant hoses with a blue mark are correct.Service

- 1. Check the valve function with compressed air (use pressure reducer max 1bar).
- 2. The flow must only go towards the reservoir and be blocked to the engine.
- 3. Replace the coolant hose if a flow to the engine is possible.

UNote:

ETKA may call for updated reservoir.

Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 				
Service Number:	1962				
Damage Code:	0010				
Labor Operations:	Replace coolant hose	19 62 55 99	50 TU		
Diagnostic Time:	GFF – Checking and clearing fault codes included in existing labor operations	No allowance	ο τυ		
	Road test prior to service procedure	0121 0002	10 TU		
	Road test after service procedure	0121 0004	10 TU		
Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowar			ance details)		

© 2017 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Claim Comment:

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
4G0 121 081 AH	Coolant hose	1
4G0 121 403 G	Reservoir	1 (If ETKA advises)

Additional Information

All parts and service references provided in this TSB (2030623) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2017 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.