



Technical Service Bulletin

27 Vibrations felt at 1000 rpm and 3000 rpm

27 17 29 2036392/6 March 31, 2017. Supersedes Technical Service Bulletin Group 27 number 16-27 dated October 31, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
S6, S7, RS 7, A8, S8	2013 - 2015	All	4.0 TFSI

Condition

REVISION HISTORY		
Revision	Date	Purpose
6	-	Revised Warranty (Updated Labor Operations)
5	10/31/2016	Revised <i>Service</i> (Revised entire section)
4	03/20/2015	Revised header data (Added model years) Revised <i>Service</i> (Revised entire section) Revised Warranty (Updated Labor Operations)

- Vibrations are felt at 1000 rpm and 3000 rpm.

The following DTCs may be stored in the sub-frame mount control module, J931 (address word 00BA):

- **DTC B201000** (No basic setting)
- **DTC B200500** (Data record invalid)

Technical Background

The basic settings of the active engine mounts in the sub-frame mount control module, J931, are deactivated when work is done on either of the vehicle electrical system control modules, J519 and/or J520 (for example, when a key is programmed). As a result, the vehicle vibrates or judders when cylinders are actively switched off.



Technical Service Bulletin

Production Solution

Optimized J931 control module software.

Service

Before proceeding, attempt to verify the vibration concern by performing a test drive. During the test drive, observe the vehicle in the following conditions:

- In 3rd or 4th gear (tip mode) at 2500 to 3200 rpm.
- Approximately 50% throttle input.

If the condition cannot be reproduced, this bulletin does not apply.

If the condition can be reproduced, follow the instructions for the appropriate model below:

For S6, S7, and RS 7:

Update the J931 control module:

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the J931 control module using the SVM action code as listed in the table below, if necessary:

Model	Engine	Old Software Part Number	Old Software Version (or lower)	New Software Part Number	New Software Version (or higher)	SVM Code Input
S6, S7, RS 7	4.0T	4H0907145	0006	4H0907145B	0008	BAA001

3. Perform J931 basic settings after SVM is completed.



Tip: If J931 basic settings are not performed after the SVM update, the motor mounts will not properly dampen engine movement and the claim will be denied.

4. If condition *is* eliminated, release the vehicle.

For A8 and S8:

Update the J931 control module:

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.

Technical Service Bulletin

2. Update the J931 control module using the SVM action code as listed in the table below, if necessary:

Model	Engine	Old Software Part Number	Old Software Version (or lower)	New Software Part Number	New Software Version (or higher)	SVM Code Input
A8, S8	4.0T	4H0907145	0006	4H0907145B	0008	BAA001

3. Perform J931 basic settings after SVM is completed.



Tip: If J931 basic settings are not performed after the SVM update, the motor mounts will not properly dampen engine movement and the claim will be denied.

4. Align the exhaust system according to Elsa at *Repair Manual >> Engine >> Engine Mechanical, Fuel Injection and Ignition >> 26 Exhaust Systems, Emission Controls >> Exhaust System, Installing without Tension.*
5. Perform J931 basic settings after aligning the exhaust.
6.
 - If condition *is* eliminated, release the vehicle.
 - If condition *is not* eliminated, perform TSB 2045720: *26 A8/S8 4.0TFSI, vibrations between 1000 and 3000 rpm while driving.*
 - a. If condition *is* eliminated after performing the TSB, release the vehicle.



Technical Service Bulletin

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	1039		
Damage Code:	0041		
Labor Operations:	SVM update	1039 2599	Time stated on diagnostic protocol (Max 50 TU)
	Check SVM update already performed	2470 0199	10 TU
	Align exhaust system after J931 basic setting	2625 9999	20 TU
Diagnostic Time:	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2036392/6		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2036392) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2045720, *26 A8/S8 4.0TFSI, vibrations between 1000 and 3000 rpm while driving.*

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of



Technical Service Bulletin

Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.