



# Technical Service Bulletin

---

## 91 Predictive route data fault (DTC B163002) stored in the MIB Main Unit - A4/Q7

91 17 12 2047112/1 March 9, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2017 - 2018	All	Not Applicable
Q7	2017 - 2018	All	Not Applicable

## Condition

Customer may report a warning in the Driver Information System (DIS) about ACC or a concern about the MMI main unit.

### Workshop findings:

The following DTC may appear in the information electronics control module 1 (J794) (address word 005F):

- **DTC B163002** (predictive route data signal error)

## Technical Background

If the DTC is sporadic, it is an information only DTC, it indicates the vehicle was operated in an area where no predictive street data was provided and thus the vehicle functions requiring this information would not be active.

Affected vehicle functions can include, but are not limited to:

- Efficiency mode/assist
- Adaptive cruise control
- Adaptive lighting
- Traffic Jam assist

# Technical Service Bulletin

---

## DTC memory entry

Number:	predictive route data Signal error (B163002)
Error type 2:	passive/sporadic
Symptom:	1123600
Status:	00001000

**Figure 1.** Example of DTC memory entry.

If the DTC is Static, pursue other troubleshooting steps to find the root cause. Some questions that may help diagnose the concern:

- General location of the driver when they received the warning in the DIS?
- What were the driving conditions?
- Is the warning that the customer received in the owner's manual?
- Does the fault code time/date match the customer description?

## Production Solution

Not applicable.

## Service

Do not replace parts for a sporadic fault, this will not fix the condition. See Technical Background for more information. Warranty claims that are submitted for this DTC and condition may be rejected.

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.



# Technical Service Bulletin

---

## Additional Information

All parts and service references provided in this TSB (2047112) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.