

Technical Service Webinar

April, 2017

Technical Service Webinar

All information discussed is already published and is being discussed as diagnostic aids. Please always review the most current publications for current information.

We will not be discussing specific vehicles, please use TAC tickets for this.

We are using the webinars as a way to increase communication to dealerships and technicians. This is a result of feedback from the dealer sub council

What's New:


- > **2018 Q5 Launch Details**
- > **3.0L Repair Authorization**
- > **TSB 2046986 Q7 brake noise PSS**

Diagnostic Tips:

- > **Clearing Passive Faults**
- > **Identifying the CYMC engine on the new A5**
- > **TSB 2045673 Internal processor Faults**
- > **TD1 Detection**

Feedback:

- > **Topic reviews**
- > **Q&A**
- > **Do you have any topics you would like covered?**
- > **Submit feedback to artactivation@audi.com**



What's New

April, 2017

2018 Q5 Launch

Launch overview

This will be the largest volume Audi of America launch to date.

12,000+ Initial launch volume

17,000+ expected to be sold by the end of the launch

We ask for your support in identifying product issues.



Together, we will be able to resolve issues quickly and provide our customers the level of quality they have come to expect from the Audi brand

2018 Q5 Launch Repair Authorization

- › Vehicle launch has started and will run for approximately 12 weeks.
- › All repairs on the 2018 Q5 require authorization through TAC
- › Verify Customer Concern.
- › Begin GFF diagnosis. **Do not** remove any part or disconnect electrical connections until instructed to do so.
- › Create a TAC ticket using the Technical Assistance Center System in Elsa.
- › Select New Audi Q5 Launch Repair Authorization in the Concern Type field for proper routing to our launch-dedicated TAC Consultant.
- › Describe the customer concern with as much detail as possible. Fill in all required fields.
- › Please include your cell phone number in the TAC ticket. The TAC consultant will use this number to contact you so you can be close to the car during the conversation.

Note: Web cases are suggested for simple repairs

2018 Q5 Launch

ILT and SSP's

The following SSP's are available:

- 990173 The 2018 Q5 Introduction
- 990173B Test
- 950273 Audi Quattro with ultra technology

Instructor led course code:

- 990172

Pre-requisites for ILT course:

- 990173
- 950273
- Networking



TSB 2047204/1

Repair Authorization for the new 3.0L Turbo V6 TFSI


Audi of America is requesting your cooperation in supplying us with the technical information vital to the successful launch of the all new 3.0 EA839 V6 TFSI engine.

Applies to:

2018 3.0 S4, S5, S5 Cabriolet and SQ5

This repair authorization is for Engine only.

Any repairs with the 2018 S4, S5, S5 Cab body or chassis do not require authorization at this time.




TSB 2047204/1

Repair Authorization for all new 3.0L EA839 V6 TFSI

- › Verify Customer Concern.
- › Begin GFF diagnosis. **Do not** remove any part or disconnect electrical connections until instructed to do so by TAC.
- › Create a TAC ticket and select New 3.0 Launch Repair Authorization in the Concern Type field.
- › Describe the customer concern with as much detail as possible.
- › Attach pictures into contact if necessary.
- › Please include your cell phone number in the TAC ticket. The TAC consultant will use this number to contact you.

Note: Web cases are suggested for simple repairs




TSB 2047204/1

Repair Authorization for all new 3.0L EA839 V6 TFSI

Special Features:

- Direct injection with on-demand high and low pressure systems.
- Exhaust turbocharging in inner V ("Hot Side Inside").
- Air to Air charge air cooling.
- Power output :
 - 354 hp @ 5400 - 6400 rpm
 - 369 lb ft @ 4500 rpm

Note: For more details on the new 3.0L engine see SSP 920173



TSB 2046986 PSS 46 Brake Noise

2017 Q7

Vehicle-specific service

PSS 46 Brake Noise

Transaction No.: 2046986/2

Release date: Feb 28, 2017

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header data (Added model year)
1	02/24/2017	Initial publication

Customer may report hearing a squeal noise from front brakes in the following conditions:

When:	After vehicle was parked for several hours/overnight, and usually in reverse
Speed:	Below 15 mph
Temperature:	Below 60°F

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

Explain to the Customer that a solution is forthcoming and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.

Create a PSS record in the PSS application via the Pending Service Solutions link in AccessAudi (under Related Links>>Service), or through the Technical Assistance page in ELSA.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

TSB 2046986 PSS 46 Brake Noise 2017 Q7

My Page

App Links

Communications

Library

Help

TDI Settlement Program

Welcome Justin Warner | My Account | Log Out

iAudi



Enter a Keyword

Search »

SELECT YOUR FAVORITE APPS TO CUSTOMIZE YOUR WORKSPACE

EDIT FAVORITES »



Academy
Academy site CRC
Audi Academy Video Portal



After Sales
Audi Tire Center
Audi Top Service Guide
Audi Top Service Supplies & Touch-Up Paint eStore
Audi Top Service Winner's Circle



Audi Connect
AcVDM myAudi Key User Verification Tool
Audi connect Information Hub
Audi connect SIM Management
myAudi Combined Owner Registration



Audi Experience
Audi Experience Portal



Audi Tdi Goodwill Package
Dealer Activation Guide
Goodwill Card Activation
How to Assign TDI Role



Financial Services
AFS Dealer Extranet
AFS Remarketing
Financial Handbook 2017
Lost and Misplaced Invoices
Wholesale DAS



Marketing
AfterSales MOC
Audi Brand Store
Audi Dealer Marketing Center
Audi Dealer Website and Digital Marketing
Audi collection
Stationery Ordering Site



Parts
Audi Accessories Catalog
Audi Tire Center
Audi Top Service Process Guide
Audi Top Service Supplies & Touch-Up Paint eStore
Compliance Label Ordering Portal
Parts On Command
Parts Price List
Safety Data Sheets
Sheet Metal Quality Standard Video
Warranty Parts Portal (WPP)

BOTTOM

TOP

TSB 2046986 PSS 46 Brake Noise 2017 Q7

Parts Price List
Safety Data Sheets
Sheet Metal Quality Standard Video
Warranty Parts Portal (WPP)



Service

A.U.D.I. Search
Audi Care Management System 2.0 **new!**
Audi Care/VIN Lookup
Audi Service Advantage
Audi Special Tools and Equipment
Audi Top Service Process Guide
Audi Top Service Winner's Circle
Automotive Youth Education Systems
Compliance Label Ordering Portal
DealerFX Maintenance Calculator
ElsaPro
OFF Paperless
I-Wire
ODIS - eShop
ODIS Certificate Request Mgmt System(eCRMS)
Pending Service Solutions(PSS)
SAGA System
Service Key
ServiceNet
TRAC Reporting
Technical Literature Ordering Center
Warranty Online

Takata Service Pack

Audi Incentives Portal
Takata Dealer Communication Toolkit


Track Progress

Audi Dealer Digital Readiness Program
Audi Insight
Audi Lead Intelligence
Audi Magna Society
Audi Project Tracker
Claim Inspector
Customer Information Intelligence
Dealer AftersalesIQ
Dealer Business Intelligence
Dealer Site Viewer
ISS Scorecard
MarketMaster™ Online
My Dealership Report and Pub
My Dealership Reports - Operations
My Dealership Reports - Parts
My Dealership Reports - Sales
My Dealership Reports - Service
POLK Loyalty Dashboard
Parts & Accessories Bonus Portal
Service Capacity Tool
Service IQ
Standards Management System
Today's Reports

Vehicle Sales & CPO

Audi Ascent
Audi Certified pre-owned
Audi Corporate Sales Programs
Audi Incentive Claims Portal
Audi Incentive Portal
Group Vehicle Logistics Website
QMD Web
Owner In Waiting Communications
Port of Halifax





Diagnostic Tips

April, 2017

Clearing passive faults in ODIS

2017-2018 A4, Q7, A5

Concern:

After clearing out transport mode at PDI several passive faults are unable to be cleared from the 03 module.

After performing a repair there are several passive faults stored in various modules that will not clear.

Cause:

There is an ODIS issue identified with version 4.0.0 that may not clear passive faults using the traditional methods.

Correction:

TSB 2042954 DTC U110500 (Q7 Transport mode active) cannot be cleared

Clear faults using Guided Functions of the affected control unit

Clear faults using Flash

Address: 0003 System name: 03 - Brake Electronics Log versions: UDS/ISOTP (Ereignisse: 16)

+ Identification:

- DTC memory entries:

DTC memory entry

Number:

Error type 2:

Symptom:

Status:

C11EA14: Sensor for roof rack recognition Open circuit/short circuit to ground
passive/sporadic
290560
00101100

+ Standard ambient conditions:

+ Expanded ambient conditions:

DTC memory entry

Number:

Error type 2:

Symptom:

Status:

C100C01: Electro-mechanical parking brake button Electrical error
passive/sporadic
292608
00101100

+ Standard ambient conditions:

+ Expanded ambient conditions:

DTC memory entry

Number:

Error type 2:

Symptom:

Status:

C100D13: Left Parking Brake Motor voltage supply Open circuit
passive/sporadic
294400
00101100

+ Standard ambient conditions:

+ Expanded ambient conditions:

DTC memory entry

Number:

Error type 2:

Symptom:

Status:

C100E13: Right parking brake motor voltage supply Open circuit
passive/sporadic
296192
00101100

+ Standard ambient conditions:

+ Expanded ambient conditions:

DTC memory entry

Number:

Error type 2:

Symptom:

Status:

U110500: Transport mode active
passive/sporadic
297728
00101110

+ Standard ambient conditions:

+ Expanded ambient conditions:

DTC memory entry

Number:

Error type 2:

Symptom:

Status:

U141C00: Voltage supply terminal 30 for electronics Open circuit
passive/sporadic
364032
00101100


+ Standard ambient conditions:

+ Expanded ambient conditions:

Clearing passive faults in ODIS

Clearing faults using Guided Functions


- Fresh reboot of ODIS
- Hardwire or Bluetooth may be used
- Start a new GFF session
- Cycle the key one time.
 - (key Off and On after completed GFF scan)
- Right click ABS control module
- Select Guided Functions
- Select Check and erase DTC memory.
- Follow the test plan steps to clear faults
- On control modules tab select “Read all module DTC” to assure faults are cleared



Clearing passive faults in ODIS

Clear faults using Flash

- › Exit your GFF session
- › Select and enter FLASH
- › Do not run any test
- › Then exit FLASH
 - › Flash will clear faults on exit
- › Verify if code is still present using the OBD button (it is the quickest way to verify)



NOTE: This method is best used if there are several modules with PASSIVE faults that will not clear.

Identifying the CYMC engine code 2018 A5

Concern:

When starting diagnosis on the vehicle there is no engine selection for the CYMC 2.0L engine

Cause:

ODIS does not yet have the CYMC engine code available for the A5

Correction:

The engine code CYMC for 2018 A5 will be available in a future ODIS version

In order to perform diagnosis on the CYMC engine, the A5 may be identified as an A4 and the engine code selected there.

NOTE: Since these two vehicles are very similar and largely based on the same platform, diagnosis will be supported.

vehicle basic features

Vehicle identification ☐ automatic ☒ manual

VIN

WAUTNAF57JA000738

Manufacturer

Audi

Model

Audi A5 USA/CDN 2016>

Model year

2018 (J)

Version

Coupe

Engine

☒ work with Guided Fault Finding

Apply Cancel

Identifying the CYMC engine code

2018 A5

No CYMC selection for the A5

vehicle basic features

Vehicle identification ☐ automatic ☒ manual

VIN
WAUTNAF57JA000738

Manufacturer
Audi

Model
Audi A5 USA/CDN 2016>

Model year
2018 (J)

Version
Coupe

Engine

☒ work with Guided Fault Finding



CYMC selection available for the A4

vehicle basic features

Vehicle identification ☐ automatic ☒ manual

VIN
WAUTNAF57JA000738

Manufacturer
Audi

Model
Audi A4 USA/CDN 2016>

Model year
2018 (J)

Version
Sedan

Engine
CYMC 2.0I TFSI / 185kW

☒ work with Guided Fault Finding



TSB 2045673/1

DTC P060C00 Stored in ECM

DTC P060C00: Internal Control Module Main Processor Performance stored in ECM

For the 2016 A6 A7 3.0L TFSI CREC

- Do not replace ECM as the GFF test plan directs.
- Optimized software with improved diagnostics for the A6 and A7 is now available. See TSB 2045673 for more details

For the 2017 A8 and Q7 3.0

- SVM code to come
- Please clear the DTC and road test the vehicle to ensure the DTC does not return.
- If the fault returns, create a TAC ticket and attach the latest GFF log.



TSB 2028842/2

Checking for TD1 Detection of Unauthorized Chip tuning

- To detect TD1 a specified/actual or Vehicle Configuration will need to be performed. This can be done at start of diagnosis or in special functions tab of GFF.
- This should be run when major engine or transmission repairs will be performed under Warranty or Goodwill.
- If unauthorized engine tuning is detected during the specified/actual comparison, a “TD1” code is automatically populated within the Warranty Key section of Elsa.

Test step: Software Version Management (SVM)

Campaign: SELECTION

Output: For this model, a specified/actual comparison is required at the start of Guided Fault Finding. This detects incorrect codings and parameterization and can correct them. If incorrect software or hardware is found in the control modules, SVM will provide a hardware change suggestion, but additional actions must be carried out by the technician to fix these hardware conflicts. SVM will not provide automatic software updates for control modules without a SVM code. If a specified/actual is not performed, the following GFF test plans may result in faulty repairs due to incorrect control module configurations, software or hardware. If only a software update using a SVM code is being performed, the specified/actual comparison does not need to be performed.

Should a specified/actual comparison be performed?

Entry: Yes



Thank you!