

70 Noises from headliner/sunroof area

70 17 60 2044417/4 May 17, 2017. Supersedes Technical Service Bulletin Group 70 number 17-58 dated March 8, 2017 for reasons listed below.

Model(s)	Model(s) Year VIN Range		Vehicle-Specific Equipment	
Q7	2017	All	Not Applicable	

Condition

REVISION HISTORY					
Revision	Date	Purpose			
4	-	Revised Service (Additional noise abatement procedure)			
3	03/08/2017	Revised header data (Added all MY 2017)			
2	02/10/2017	Revised Warranty (Specified claim type)			

The customer hears a rattle from the headliner area.

Technical Background

The noises can be caused by movement in the clips that attach the headliner to the sunroof frame or movement between components of the sunroof frame.

Production Solution

Felt material has been added to points of contact in production.

Service

1. Test drive the vehicle (preferably with the customer) and duplicate the noise. Applying pressure to areas of the headliner around the perimeter of the sunroof will eliminate the noise, confirming the root cause.



 Remove the headliner. The clips shown in the illustration will need fleece adhesive tape (D 373125A2) (Figure 1).



Figure 1. Location of the headliner to sunroof frame clips.

3. Remove the clips and apply the fleece adhesive tape underneath them, as shown (Figure 2).




Figure 2. Location of the fleece adhesive tape application.



4. Reinstall the clips (Figure 3).




Figure 3. Clips reinstalled.

5. Apply fleece adhesive tape to the sunroof frame lip at each clipping point (Figure 4).




Figure 4. Application area on sunroof frame area of clip engagement.



6. There are two additional points of contact at the front sunroof frame plates that could be a source for noise (Figure 5).



Figure 5. Areas of the sunroof frame to be isolated with fleece adhesive tape.

 Apply fleece adhesive tape between the sections of the sunroof frame plates on both the right and left sides as shown in the illustration (Figure 6).



Figure 6. Fleece adhesive tape applied between the side and front sunroof frame plates.

8. Perform a final test drive to confirm that the noise has been eliminated.



Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 				
Service Number:	rvice Number: 7084				
Damage Code:	0020				
Labor Operations:	Headliner remove + reinstall	7084 1900	330 TU		
	Apply fleece tape to headliner clips and sunroof frame plates	7084 9999	40 TU		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	0121 0002	10 TU		
	Road test after service procedure	0121 0004	10 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2044417/4				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
D 373125A2	D - 372 - 125 - 12 AO 018 DO3 ADHER TA	0.1
	Fleece Adhesive Tape	



Additional Information

All parts and service references provided in this TSB (2044417) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.