

Technical Service Bulletin

40 Front shock absorber cap, cracking noises/spring jumps when steering

40 17 62 2047758/1 May 18, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3, S3	2015 - 2017	All	Drive select and magnetic shock absorbers

Condition

Customer concern:

- Cracking noises/spring jumps when steering or when maneuvering.
- The noise can be reproduced when at least 2 people are in the vehicle and the steering wheel is just before the right/left stop.

Technical Background

The buffer stop for shock absorber (Figure 1,1) can cause noises if it touches the front shock absorber cap (Figure 1, 2).

Production Solution

Not applicable.

© 2017 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Service

Lightly lubricate the contact surface (red dotted line) between buffer stop for shock absorber (Figure 1, 1) and front shock absorber cap (Figure 1, 2) with silicon grease G 000 405 A2.




Figure 1. Shock absorber and buffer stop.

Tip: Check the protective sleeve of the front shock absorber for correct fit, they should turn easily in the axial deep-groove ball bearing/sleeve bearing.

Warranty

Claim Type: • 110 up to 48 Months/50,000 Miles					
	 If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 				
Service Number:	vice Number: 4098				
Damage Code:	0020				
Labor Operations:	Lubricate both front rubber stops	4098 5099	30 TU		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	No allowance	0 TU		
	Technical diagnosis at dealer's discretion				
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				

© 2017 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Claim Comment: As per TSB #2047758/1

All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
G 000 405 A2	Grease	1

Additional Information

All parts and service references provided in this TSB (2047758) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2017 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.