TECHNICAL INSTRUCTIONS

FOR

LIMITED SERVICE CAMPAIGN EOK

SAFETY CONNECT SYSTEM Disabled

CERTAIN 2014 MODEL YEAR AVALON, AVALON HYBRID, HIGHLANDER, AND SIENNA VEHICLES

All dealership associates involved in the recall process are required to successfully complete E-Learning course SC13A. To ensure that all vehicles have the repair performed correctly; technicians performing this recall repair are required to currently hold <u>at least one</u> of the following certifications levels:

- Toyota Certified (any classifications)
- Toyota Expert (any classifications)
- Master
- Master Diagnostic Technicians

I. OPERATION FLOW CHART



II. IDENTIFICATION OF AFFECTED VEHICLES

WMI	MY	Model	VDS	MIN-MAX
411	2014	Avalon	BK1EB	U085708-U093137
411	2014	Avalon Hybrid	BD1EB	U020971-U02354
		Highlandor	DKRFH	S005618-S010058
5TD	5TD 2014	Fighlander	YKRFH	S005068-S006709
		Sienna	DK3DC	S073641-S073641

NOTE:

A small number of vehicles involved in this campaign may have a DCM that has previously been activated. File a warranty claim to mark them complete.

- Always check the TIS Vehicle Inquiry System to confirm the VIN is covered by this Limited Service Campaign, and that the campaign has not already been completed by another dealer.
- <u>TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected</u> or were completed by another dealer

III. PREPARATION

A. PARTS

No parts are required to complete this campaign

B. TOOLS & EQUIPMENT

- Techstream 2.0 / TIS Techstream / Techstream Lite (Software 9.00 or Higher)
- GR8 Battery Diagnostic Station

IV. BACKGROUND

In certain 2014 Avalon, Avalon Hybrid, Highlander, and Sienna vehicles the Mobile Identification Number/Mobile Directory Number has expired or is no longer valid. The subject vehicles are equipped with Safety Connect, which allows drivers to contact the Toyota 24/7 response center at the touch of a button. Toyota has identified that the Safety Connect System in the subject vehicles has become disabled due to an unplanned expiration of the Mobile Identification Number/Mobile Directory Number.

V. REPROGRAMMING THE DCM

1. CONNECT THE GR8

- a) Set the GR8 to Power Supply Mode to maintain 13.5 volts during ECU reprogramming
- b) The charger must be connected directly to the battery



A battery charger set to power supply mode *MUST* be used during reprogramming
ECU damage may occur if the correct battery charger setting is not used

2. TURN OFF ALL ELECTRICAL ACCESORIES

a) Turn off all electrical accessories (i.e lights, audio and climate control systems)

3. CONFIRM THE IGNITION IS ON

4. VERIFY THE CONDITION

 a) Conduct a light check by pressing the SOS (Safety Connect) button. Follow the flow chart according to the light's response.



6. CHOOSE TELEMATICS FROM THE SYSTEM SELECTION MENU

File Function Setup TIS System Select Store	User Help d Data					
	System Selection Select desired system and System Yellow = ECU System White = ECU "System White w/Aste	Menu then press the arrow buttor J status unknown. communication OK. arisk = ECU not supported	n to access the ECU. or not responding.			
Health Check Customize Setting ECU Reprogramming CAN Bus Check TIS Function	All ECOS Powentalin Engine and ECT PPS D-Door Motor Master Switch Power Source Control PM2 Gateway	Cruise Control Cruise Control Air Conditioner P-Door Motor D-SEAT SW Occupant Detection Telematics	KDSS SRS Airbag RL-Door Motor Sliding Roof Remote Engine Starter	ABS/VSC/TRAC Main Body RR-Door Motor Combination Meter Starting Control	Tire Pressure Monitor Back Door P/W Driver Seat Smart Key Navigation System	
TIS Search Print Main Menu	This ECU controls the one Note: Telematics cannot co	to send/receive information	t by wireless. for approximately 20 seconds	s after IG ON.		

7. CHOOSE THE UTILITY OPTION AND CLICK THE NEXT BUTTON

	Code Description	Current	Pendina	History	Summary
	None		_		
Trouble Codes Data List					
Active Test					
Monitor Utility					
Dual Data List					
TIS Search					

8. CLICK DCM SERVICE ON THE UTILITY MENU

File Function Setup TIS System Select Store	User Help d Data Telematics Live	
	Utility Selection Menu Select desired Utility and then press Next button.	Λ
	DCM Operation History DCM Service	Ň
Trouble Codes		\sim
Active Test		
Monitor		
Dual Data List		
TIS Search		
Print Close		

9. CHOOSE ACTIVATE DCM

a) Select Activate DCM and click next to reprogram the DCM

	Utility Selection Menu Select desired Utility and these more black butter	1
Trouble Codes Data List Active Teat Monitor Utility Dual Data List	DCM Service (IOCN:01:001) DCM Operation Hi Customize Welcome to the DCM Service utility. This utility can perform the following service functions. Please select a service operation below. Activate DCM C ACN call end Press Next to start.	
TIS Keyword Print Close	<pre></pre> <pre></pre> <pre></pre> <pre> </pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre> <pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre></pre>	

10. VERIFY THE DCM IS NOW ACTIVATED

a) Press the SOS (Safety Connect) button and confirm the vehicle connects to the Toyota call center

11. PRINT CUSTOMER HEALTH CHECK REPORT

 a) From the Health Check Results screen select the Customer Health Check Report button (TIS will launch when button is pressed)

Techstream (Ver 8. Ele Exection Setur	00.023) - 11067			
System Select Stor	od Data		Customer Health	
2010 Prius 2ZR FXE UTDIXICUBA1010058 2010, Prius 2ZR File Notes Health Check	Tire Pressure / Threshold Value [psi[gauge]] Sensor 1: 27.5 / N/A Sensor 2: 29.0 / N/A Sensor 3: 27.5 / N/A Sensor 4: 30.1 / N/A Sensor 3: 27.5 / N/A Sensor 4: 30.1 / N/A Health Check Results Monitor DTC Curr Pend 18	st Perm SB Calibration Upd	Customer Health Check Button	
500 FeV	Engine and ECT inc	34715100 2 A47031000 2 896834701800 Ve 896844701800 Ve 898844701400 Ve 89884470400 Ve		
	ABSC/SC/TRAC	F152647106 2 830004737004 830004737004 830004737004 830004737004	6	
Sort Expand>> TIS Search Print	D.Door Motor - Smart Kity - P.Door Motor - RR.Door Motor - Master.Switch - 2014/01/21 18:18:35 -		2	
Back Back	Campaign Status:2	Default User	\mathbf{A}	
d) Che serv e) Sele	ck the "Performed" campaign rac ice event ct the Report button	der number dio button for the a	applicable campaign	s completed during t
		Di	iagnostic F	Report
	Vehicl	e Informatio	n	
	Mileage	: 7787		
	Repair Order	77888		
	Our systems show the follow any of these campaigns been unsure.)	wing campaigns are outs en completed? (Check for	tanding. Have SSC door label if	
	EOF 90B	• Performed • Not Pe	rformed	
	•			
f) Cont	firm Customer Health Check Rep	port information is	correct	
h) Sign	and provide to the customer			

◄ VERIFY REPAIR QUALITY ►

- Confirm the GR8 is set up properly prior to beginning the reprogramming
- Confirm the Safety Connect System is operational
- Confirm the reflash completes successfully
- Confirm there are no DTCs in the ECU

If you have any questions regarding this update, please contact your regional representative

VI. APPENDIX

A. CAMPAIGN DESIGNATION DECODER

