

**ATTENTION:**

GENERAL MANAGER ☐  
 PARTS MANAGER ☐  
 CLAIMS PERSONNEL ☐  
 SERVICE MANAGER ☐

IMPORTANT - All  
 Service Personnel  
 Should Read and  
 Initial in the boxes  
 provided, right.

|  |  |  |
|--|--|--|
|  |  |  |
|  |  |  |

© 2017 Subaru of America, Inc. All rights reserved.



**SUBARU**

QUALITY DRIVEN® SERVICE

## SERVICE BULLETIN

**APPLICABILITY:** 2010-2014MY Legacy and Outback

**NUMBER:** 06-58-17

**SUBJECT:** Electronic Parking Brake (EPB)  
 Inoperative / DTC C0251

**DATE:** 02/16/17

### INTRODUCTION:

This bulletin announces a new replacement EPB actuator assembly to address DTC C0251. In isolated cases, the automatic calibration function of the EPB actuator may not always occur when turning the ignition on. As a **temporary** result, the EPB may not function, the brake system warning lamp will flash to alert the driver and DTC C0251 will be stored in memory. The EPB will resume normal operation on the next key cycle.

### PART INFORMATION:

| Description        | Part Number | Applicability       |
|--------------------|-------------|---------------------|
| ACTUATOR ASSY- EPB | 26002AJ01D  | 2010-2012MY         |
|                    | 26002AJ02C  | 2013 & 2014MY       |
| SELF-LOCKING NUT   | 023508000   | ALL (Qty. 4 Req'd.) |

Combination Meter Brake  
 System Warning Lamp

BRAKE / (!)

### SERVICE PROCEDURE / INFORMATION:

When replacing the EPB2 Actuator assembly, follow the complete Service Procedure in the applicable Service Manual.

### IMPORTANT NOTES:

- As part of the service procedure, the fuel tank protector will need to be removed. The 4 self-locking nuts securing the protector are **One-Time Use** items and must be replaced at re-assembly. The torque specification for these nuts is 9 Nm (6.6 foot-lbs.).
- After EPB actuator assembly installation is complete, the Force Sensor Calibration Mode must be performed with the Subaru Select Monitor following the procedure in the applicable Service Manual.

*Continued...*

#### CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

#### SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

**WARRANTY / CLAIM INFORMATION:**

For vehicles within the Basic New Car Limited Warranty period or covered by an active Subaru Added Security Gold plan, this repair may be submitted using the following claim information:

| Labor Description                        | Labor Operation # | Labor Time | Fail Code |
|--|-------------------|------------|-----------|
| EPB ACTUATOR / CM ASSEMBLY R&R           | B544-251          | 1.0        | SDP-43    |
| CM VERSION UPDATE AT TIME OF REPLACEMENT | C860-118          | 0.3        |           |
| EPB TESTING and DIAGNOSIS                | C544200           | 0.4        |           |

**IMPORTANT REMINDERS:**

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.