

Subject		Market	
Diagnosis of Bluetooth® Connectivity Complaints		USA	
Service Category		Section	
Audio/Visual/Telematics		Cellular Communication	
Applicability			
2010 - 2018 Models			

APPLICABLE VEHICLES

2015-2018	RC F	2015-2018	RC350
2015-2018	NX300H	2010-2015	IS250C
2012	LFA	2008-2016	LS600H
2018	GS300	2018	LC500
2018	LC500H	2006-2015	IS250
2016-2017	GS200T	2016-2018	IS300
2015-2017	NX200T	2008-2011	GS460
2007-2011, 2013-2018	GS450H	2010-2012	HS250H
2013-2018	ES300H	2016-2018	GS F
2007-2018	ES350	2007-2017	LS460
2010-2018	GX460	2016-2018	RC300
2010-2018	RX450H	2018	NX300
2007-2011, 2013-2018	GS350	2011-2018	CT200H
2006-2018	IS350	2010-2018	RX350
2016-2017	IS200T	2010-2015	IS350C
2008-2014	IS F	2016-2017	RC200T
2008-2011, 2013-2018	LX570		

CONDITION

Some customers may encounter Bluetooth® connectivity concerns such as:

- Difficulty to pair the phone.
- Intermittent Bluetooth® failure to connect to the vehicle when first turning on the vehicle.
- Various Bluetooth® Audio functions are no longer functioning with customer's phone such as ability to change the track using the steering wheel controls.

These concerns can be caused by changes made on the customer's phone. Make sure to inquire with the customer if the connectivity concerns occurred after receiving an operating system update on their phone or if they have restored their phone data/settings recently.

RECOMMENDATIONS

- Check for Tech Tips and TSBs which may address certain Bluetooth® concerns with the vehicle's multimedia system.
- Confirm known good phone in customer's vehicle. If known good phone experiences the same

Subject	Market
Diagnosis of Bluetooth® Connectivity Complaints	USA
Applicability	
2010 - 2018 Models	

RECOMMENDATIONS

condition, the vehicle system should be diagnosed using the vehicle's repair manual.

- If known good phone does not experience the condition in the customer's vehicle, no repair should be attempted to the vehicle. The following steps can be performed to resolve the most common phone side issues.
 - Confirm if phone has been tested for phone compatibility by going to TIS homepage and Clicking on Toyota Bluetooth® Compatibility Information link under Service Resources. If the phone did not pass compatibility testing for the customer's concern please explain the phone's limitation to the customer.
 - Disable and re-enable Bluetooth® on the phone.
 - Perform "Delete all personal data" on navigation/display audio equipped vehicles.
 - Delete all Bluetooth® paired devices on the customer's phone.
 - Soft reset customer's phone or pull the battery out of the phone.
- If the condition continues to occur only with the customer's phone then the next steps are recommended before handset replacement. **The customer should do this themselves as this will cause their customizations/network connections to be lost.**
 - For iOS 7.0 and later, the customer can go to Settings, General, Reset, Choose "Reset all Settings"
 - For most Android devices running 6.0 and later the customer can go to go to Settings, scroll right over to the Personal tab, choose Backup and reset, then "Reset network settings". For older devices which do not have this option you will have to skip this step.
 - For Samsung phones running OS 7.0, go to Settings, General Management, Reset, then go to "Reset network settings".
- If the condition continues to occur only with the customer's phone then the only step left before handset replacement is full system reset. **The customer should do this themselves as it will cause data full loss on both Android and Apple devices. Customer should first backup their phone and data before proceeding.**
 - For iOS 8.0 and later, the customer can go to Settings, General, Reset, Choose "Erase all Content and Settings"
 - For most Android devices running 6.0 the settings screen is divided into Tabs. The customer can go to Settings, scroll right over to the Personal tab, choose Backup and reset, then "Factory data reset".
 - For Samsung phones running OS 7.0, go to Settings, General Management, Reset, then "Factory data reset".
- Customer should first try Bluetooth® operation before restoring their phone. If Bluetooth® issues are resolved then some software setting or program was causing the concern. If condition is not resolved then the customer should contact the phone carrier or phone manufacturer for support.

LINK REFERENCES



Subject	Market
Diagnosis of Bluetooth® Connectivity Complaints	USA
Applicability	
2010 - 2018 Models	

This Tech Tip does not contain any link references