Rev2

July 8, 2014



# **Front Brake Vibration**

Service

Category Brake

Section Brake (front) Market USA



### **Applicability**

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2011 – 2017	Sienna	

### **REVISION NOTICE**

September 19, 2017 Rev2:

Applicability has been updated to include 2017 model year Sienna vehicles.

August 2, 2016 Rev1:

• Applicability has been updated to include 2015 - 2016 model year Sienna vehicles.

Any previous printed versions of this bulletin should be discarded.

### Introduction

Some 2011 – 2017 model year Sienna vehicles may exhibit a vibration/pulsation from the front brakes that can be felt in the brake pedal while lightly applying the brake pedal. Follow the Repair Procedure in this bulletin to address this condition.

### **Parts Information**

PART NUMBER		PART NAME	
PREVIOUS	NEW	PARI NAME	
04465-0E010	04465-45040	Pad Kit, Brake Front	
04945-0E040		Shim Kit, Anti-squeal, FR	
43512-0E030		Disc, Front	2
53851-08010		Pad, Front Wheel Opening Extension, RH	
53852-08010		Pad, Front Wheel Opening Extension, LH	

### **Warranty Information**

**TOYOTA** 

OP CODE	DESCRIPTION		OFP	T1	T2
BR1401	R & R Front Disc Pad W/Anti-squeal Shim Kit (Both Sides)	0.8	43512-0E030 04465-0E010	OD C	9
Combo A	Extension Pad Modification	0.5	53851-08010 53852-08010	9B	99

### **APPLICABLE WARRANTY**

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

### **Repair Procedure**

1. Conduct a road test to verify there is front brake vibration.

#### NOTE

The condition usually occurs when the vehicle is driven on decline/downhill.

2. Modify the front extension pads and reinstall on the vehicle.

### **NOTE**


Modification MUST be completed on both the passenger and driver side of the vehicle.

**TOYOTA** 

## **Repair Procedure (Continued)**

A. Locate the front wheel opening extension pad.

Figure 1.





B. Remove the four bolts and the extension pad.

Figure 2.




**TOYOTA** 

## **Repair Procedure (Continued)**

C. Place the extension pad on a flat surface for modification.

Figure 3.



**TOYOTA** 


### **Repair Procedure (Continued)**

D. Using a power saw, cut at the location shown.

### **NOTE**

- It is recommended to draw a straight line where the cut will be made.
- · Callout 1 as shown should be discarded.

Figure 4.



1 Discard

Reinstall on the Vehicle

E. Install the modified extension pad back on the vehicle and reinstall the fourth remaining bolt to the original location as shown.

### **NOTE**

Make sure modification is completed on both sides.

Figure 5.



TOYOTA


### **Repair Procedure (Continued)**

- 3. The NEW rotor MUST be phase matched to the hub assembly.
  - A. Mount the rotor onto the hub assembly and note the starting lug position.
  - B. Measure the runout of the hub and rotor assembly at the outermost point of the rotor surface and record the runout measurement.
  - C. Rotate the rotor clockwise on the hub to the next lug position.
  - D. Repeat step B at each lug position.
  - E. The rotor position will be determined based on the lowest runout measurement obtained.

    Max Runout Allowed: 0.05 mm (0.00197 in.)
- 4. Replace the original brake pads with the newly developed brake pads and shim kit.
- 5. Install the front wheel and torque to specification using the correct tightening sequence.

Torque: 103 N\*m (1050 kgf\*cm, 76 ft\*lbf)

Figure 6.



#### NOTICE

Do NOT use an impact gun to tighten the lug nuts; use a torque wrench and follow the correct sequence to tighten the wheels.

6. Test drive the vehicle and confirm that the condition is no longer present.