



Technical Service Bulletin

94 Rear lights do not switch from bumper to hatchgate

94 17 92 2047618/2 November 1, 2017. Supersedes Technical Service Bulletin Group 94 number 17-87 dated April 25, 2017 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017	010120 - 999999	Not Applicable
Q7	2018	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Add MY 2018 Q7)
1	04/25/2017	Initial publication

Customer may report:

- When the rear lid is closed, the lights in the rear bumper do not switch over to the main lights on the rear lid.
- The error message “Vehicle lights: malfunction! Please contact Service” intermittently appears in the driver information system (Figure 1).
- All of the rear light bulbs are fully functional. None are found to be faulty or incorrect.



Figure 1. Error message.

Workshop Findings:

The following DTC may be stored in the comfort system central control module, J393 (address 0046):

- **DTC B146C29** (Rear lid -closed- sensor Implausible signal)

Technical Background

A solution is being prepared.



Technical Service Bulletin

Production Solution

A solution is being prepared.

Service

1. Press down the striker cover on the loading sill cover -A- (Figure 4).



Figure 4. Striker cover opening.

2. Blow out any debris that might be causing an obstruction with compressed air (Figure 5).



Figure 5. Debris trapped in the Rear Lid Closed Sensor.



Technical Service Bulletin

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	5555		
Damage Code:	0010		
Labor Operations:	Clear debris from Rear Lid Closed Sensor G525 / G526	5555 9999	30 TU
Diagnostic Time:	GFF	0150 0000	20 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2047618/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2047618) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.