

## Friction noise on left side of stretch cover for both driver seat backrests when deflating dynamic seat

---

Topic number	LI91.10-P-065541
Version	1
Design group	91.10 Front seats
Date	01-13-2017
Validity	Model series X222 (Maybach)
Reason for change	
Reason for block	

---

### Complaint:

Friction noise on left side of stretch cover for front seat backrest when deflating dynamic seat

### Cause:

The stretch cover may generate friction noise at the eyelet of wire hooked into backrest

### Remedy:

1. Dismantle backrest trim (see AR91.10-p-1910lf)
2. Remove hook-in wire (Pic. 1) from left seat (Pic. 2)
3. Felt strip (A 001 983 23 10 - Cut felt strip 40x2) to length of 20 mm and fix in place around eyelet for hook-in wire (Pic. 3, Pic. 4)
4. Reinstall hook-in wire
5. Mount backrest trim (see AR91.10-p-1910lf)

Attachments	
File	Description
1.jpg	Pic. 1: Hook-in wire, left
2.jpg	Pic. 2: Position of hook-in wire at left
3.jpg	Pic. 3: Hook-in wire for eyelet, right
4.jpg	Pic. 4: Felt on hook-in wire for eyelet, right

### Symptoms

Body / Seat / Multicontour seat / Noise

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 001 983 23 10			Felt strip 40x2	1	20 mm	X

# XENTRY TIPS

## WIS-References

Document number	Title	Note	Allocation
AR91.10-p-1910lf	Remove/install seat-back lining on front seat backrest		Remedy

## Attachments

1.jpg:



2.jpg:



3.jpg:



# XENTRY TIPS

---

4.jpg:

