
TIS Service Bulletin Page 1 of 3



December 2017 Technical Service

NBT EVO CHANGES BETWEEN SELECTIONS BY ITSELF WITHOUT DRIVER INPUT- GHOST BEHAVIOR

MODEL

F22 (2 Series Coupe)	F23 (2 Series Convertible)	F30 (3 Series Sedan)	F31 (3 Series Sport Wagon)
F32 (4 Series Coupe)	F33 (4 Series Convertible)	F34 (3 Series Gran Turismo)	F36 (4 Series Gran Coupe)
F80 (M3 Sedan)	F82 (M4 Coupe)	F83 (M4 Convertible)	F87 (M2 Coupe)

Vehicles equipped with Navigation Professional (SA 609) produced from 07/01/2017 - 11/15/17.

SITUATION

The Central Information Display (CID) changes between selections (ghost behavior) and sounds an audio tone without the CID Screen being touched.

The audio tone heard is the same one that sounds when you touch the CID with your finger to make a 'touch' selection.

CAUSE

Faulty Central Information Display.

CORRECTION

Replace the Central Information Display.

PROCEDURE

For conditions that are similar to the situation described:

- 1. Perform diagnosis with the latest version of ISTA and work through the corresponding test module. Complete any required repairs.
- 2. If CID continues "ghost behavior", replace the Central Information Display with part number 65 50 8 709 338 or its supersession.

Note that ISTA 4 will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW-approved battery charger/power supply (SI B04 23 10).

For information on programming and coding with ISTA, refer to CenterNet / TIS / Technical Documentation / Diagnostics and Programming / Programming Documentation.

PARTS INFORMATION

Description Part Number Quantity	Description	Part Number	Quantity
----------------------------------	-------------	-------------	----------

TIS Service Bulletin Page 2 of 3

Central Information Display 65 50 8 709 338 (or its supersession) 1	
---	--

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

Defect Code:	6552001800	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2	Performing "vehicle test" (with vehicle diagnosis system – checking faults) (Main work)
Or:		
00 00 556	Refer to KSD2	Performing "vehicle test" (with vehicle diagnosis system – checking faults) (Plus work)
And:		
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply (indicated in KSD2 as "Charging battery")
And, as necessary:		
61 00 006	Work time (WT)	Performing vehicle diagnosis – test module
And:		
65 50 558	Refer to KSD2	Replacing Central Information display
And:		
61 00 730	Refer to KSD2	Programming / encoding control unit(s)

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006

Work time labor operation code 61 00 006 is not considered a Main labor operation; however, it does require an individual punch time and an explanation on the repair order and in the claim comments section.

And, additionally for the:

e-Vehicle

Labor Operation:	Labor Allowance:	Description:
61 25 910	Refer to KSD2	Recharging high-voltage battery unit (to high voltage charging socket)

Refer to KSD2/AIR for the corresponding flat rate unit (FRU) allowances.

During the same workshop visit, if a vehicle also requires another Technical Campaign or repair that also

TIS Service Bulletin Page 3 of 3

includes programming and encoding the control units, the programming procedure may only be invoiced one time.

Vehicle Programming and Encoding

ISTA automatically reprograms and encodes all the vehicle control modules that do not have the latest software i-level. If one or more control module failures occur "during" this programming procedure:

• Please claim this "consequential" control module-related repair work under the defect code listed in this bulletin with the applicable KSD2/AIR labor operations.

Control module failures that occurred "prior" to performing this programming procedure:

• When "covered" under an applicable limited warranty, claim this control module-related repair work using the applicable defect code and labor operations in KSD2/AIR.

Other Repairs

Under the terms of the BMW New Vehicle Limited Warranty, if other eligible and covered work is performed as a result of performing the ISTA diagnostics and the related test plans, claim this work with the defect code and labor operations from KSD2/AIR that apply (including diagnosis with separate punch times, when applicable).

[Copyright ©2017 BMW of North America, Inc.]