



Service Bulletin

TECHNICAL

Subject: Intermittent Vehicle Pulls While Driving

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2016	2017				

Involved Region or Country	North America and N.A. Export Regions
Condition	Some customers may comment on an intermittent vehicle pull while driving. The pull may be either direction or it may also change directions in subsequent drive cycles.
Cause	This condition may be caused by a software anomaly.
Correction	An updated software calibration has been released to address this condition.

Warranty Information

Labor Operation	Description	Labor Time
2810625	Power Steering Control Module Reprogramming with SPS	Use Published Labor Operation Time

Service Procedure

Reprogram the power steering control module with the latest calibrations available on TIS2WEB. Refer to *Power Steering Control Module Programming and Setup* in SI.

Important: Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install the *EL-49642* SPS Programming Support Tool to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. **DO NOT** connect a battery charger.

Version	2
Modified	May 2, 2017 – Adding the 2017 Model Year.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the

equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION