


Service Bulletin

TECHNICAL

Subject: Incorrect Display of Fuel Economy Units Displayed on Driver Information Center (DIC)

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT6	2016	2017				
	CTS	2016	2016				
	Escalade Models						

Involved Region or Country	Japan
Additional Options (RPOs)	UDV, UHS
Condition	Some customers may comment that the display for fuel economy units in the Driver Information Center may be displayed in L/KM .
Cause	This condition may be caused by a software anomaly in the Instrument Panel Cluster (IPC).



Parts Information

No parts are required for this repair.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Labor Operation Time

Service Procedure

Refer to Instrument Cluster Programming and Setup in SI.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION