

Date: Mar-2017



TECHNICAL

Subject: Side Blind Zone is Not Working Correctly and/or Incorrect Side Mirror Notification

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Bolt EV	2017	2017				
Opel	Ampera-e	2017	2017				

Involved Region or Country	North America, Europe	
Additional Options (RPOs)	Equipped with Side Active Safety Obstacle Detection Enhanced (RPO UKC)	
Condition	Some customers may comment when driving, the side mirror indicates there is a vehicle present when there actually is not. This condition may be experienced after rear fascia replacement.	
Cause	This condition may be due to the object sensing alert module missing the single piece of aluminum butyl tape that is located on the bottom of both left and right module bracket.	

Correction





Install a new single piece of aluminum butyl tape on the bottom of the object sensing alert module brackets.

Parts Information

Description	Part Number	Qty
TAPE-RR BPR FASCIA EXTN	42563361 (LH)	1
	42563362 (RH)	

Warranty Information

Labor Operation	Description	Labor Time	
6480398*	Apply Butyl Tape to Both Object Sensing Modules	0.4 hr	
*This is a unique Labor Operation for Bulletin use only.			

Service Procedure

- 1. Raise the vehicle to its full height. Refer to Lifting and Jacking the Vehicle in SI.
- 2. Using Acrysol or equivalent, clean the bottom of the module and allow to dry.
- 3. Peel the backing off of the aluminum butyl tape and apply to the bottom of the module.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

