

## **Service Bulletin**

File in Section:

Bulletin No.: 17-NA-343

Date: November, 2017

## **INFORMATION**

Subject: Information on Weak or Discharged Battery After Flat or Dinghy Towing the Vehicle

Attention: This Bulletin only applies to vehicles equipped with the LYX engine with FWD or the LH7 engine with FWD or AWD.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Branu.	woder.	from	to	from	to		
Chevrolet	Equinox	2018	2018			1.6L Diesel (LH7) and 1.5L (LYX)	

Involved Region or Country	North America and N.A. Export Regions			
Condition	Some customers may comment that the battery is weak or discharged after flat or dinghy towing the vehicle.			
Cause	This condition may be caused by the vehicle calibration not allowing the vehicle to power down for towing.			
	Important: When installing a battery charger. It will be required to install the charger cables to the battery jump post and not the battery clamps.  Note: Reference the owner manual to determine if the vehicle is flat/dinghy tow capable.			
Information	Install a battery maintainer onto the tow vehicle and connect the charger leads to the vehicle.			
	⇒ Example Product: https://rvibrake.com/products/towed-battery-charger? variant=8804388741			
	⇒ This will maintain the battery of the Equinox while towing.			

## **Parts Information**

No parts are required for this repair.

Version	1
Modified	Released November 8, 2017

