

Service Bulletin

File in Section:

Bulletin No.: 17-NA-373

Date: November, 2017


TECHNICAL

Subject: Malfunction Indicator Lamp (MIL) Illuminated and DTC P0071 Set at PDI

Brand:	Brand: Model:		Model Year:		VIN:		Transmission:
Біапи.	woder.	from	to	from	to		
Buick	Encore	2017	2017			LE2	All

Involved Region or Country	North America and N.A. Export Regions	
Additional Options (RPOs)	Equipped with 1.4L Turbo 4 Cylinder Engine (RPO LE2)	
Condition	Some technicians may notice a malfunction indicator lamp (MIL) illuminated at PDI. During diagnosis, a technician may find DTC P0071 set in the engine control module.	
Cause	This may be due to the vehicle being built with the incorrect ambient air temperature sensor.	
Correction	Replace the ambient air temperature sensor.	

Service Procedure



4531838

If you encounter a vehicle with the above concern, remove and inspect the ambient air temperature sensor. Refer to *Ambient Air Temperature Sensor Replacement* in SI.

- If the part number on the ambient air temperature sensor is 13583411, continue diagnosis referring to SI.
- If the part number is anything other than part number 13583411, replace the sensor.

Parts Information

Causal Part	Description	Part Number	Qty
Х	SENSOR ASM- AMB AIR TEMP	13583411	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time	
3432010	Ambient Air Temperature Sensor Replacement	Use Published Labor Operation Time	

Version	1
Modified	Released November 21, 2017