

Service Bulletin

File in Section:

Bulletin No.: 17-NA-363

Date: November, 2017

TECHNICAL

Subject: OnStar LED is Red, Poor/No Voice Recognition, Inoperative Hands-Free Microphone During Bluetooth and OnStar Calls - DTC B2455 04 Set

	Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
			from	to	from	to		
	Chevrolet	Equinox	2018	2018				

Involved Region or Country	North America			
Additional Options (RPOs)	IOB, IO5, IO6			
Condition	Some customers may comment on: RED OnStar LED Poor/no voice recognition Hands-Free Microphone inoperative during Bluetooth and/or OnStar Calls Some Technicians may find DTC B2455 04 set			
Cause	This condition may be caused by a poor connection on terminal 11 (Circuit 655 for Cellular Telephone Microphone Signal) and/or 12 (Circuit 654 for Cellular Telephone Microphone Low Reference) at the X404 connector.			
Correction	If this concern is encountered, inspect terminals 11 and 12 at the X404 connector for poor			
	If this concern is encountered, inspect terminals 11 and 12 at the X404 connector for poor terminal tension, bent terminals, or backed out terminals.			

Copyright 2017 General Motors LLC. All Rights Reserved.

Service Procedure

Refer to Repairing Connector Terminals (Terminal Repair) in SI.

Refer to the table below to aid in diagnostics and repair.

Document ID:	Subject:
4595037	X404 Headliner Harness to Body Harness (Connector end view for X404)
4587033	Body Harness Routing - Right Rear of the Passenger Compartment (Connector Location = Item 2 in Grid C-13)
2777046	DTC B2455, SI Diagnosis (IO5/IO6/IOB)
4600271	Controls and Audio Signals (Schematic for Circuits 654 and 655 – X404)

Parts Information

No parts are required for this repair.

Warranty Information

For wiring repairs covered under warranty, please refer to latest version of Bulletin 10-00-89-005 for warranty information on wire/connector repairs.

Version	1
Modified	Released November 17,2017