

Service Bulletin

File in Section:

Bulletin No.: 17-NA-364

Date: November, 2017

TECHNICAL

Subject: Rattle Noise Originating from Driver Side Rear Seat

	Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
			from	to	from	to		
	Buick	Envision	2015	2018			All	All

Involved Region or Country	North America and China		
Condition	Some customers may comment on a rattle type noise originating from the driver side rear seat. This may be due to the cushion side member touching the frame tube creating a rattle type noise.		
Cause			
Correction	13 08 20 B		
	4804		

Page 2 November, 2017 Bulletin No.: 17-NA-364



Add felt tape to the frame tube.

4894051

Service Procedure

If you encounter a vehicle with the above concern, complete the following steps:





4894046

4894044

Cut two 3 inch (7.6 mm) strips of Kent BRS Tape (part number KT - 13295).

Bulletin No.: 17-NA-364 November, 2017 Page 3



4894048

Visually inspect the bottom of the seat and install the strips of BRS tape on both ends of the seat bar as illustrated above.

Parts Information

Order BRS Tape from Kent Automotive at 1-888-YES-KENT, or online at www.kent-automotive.com.

Causal	Description	Part	Material
Part		Number	Allowance
N/A*	Kent Automotive BRS Tape	KT - 13295	\$1.00 (U.S.) \$1.50 (Canada)

^{*}For warranty transactions, DO NOT mark this/these parts as the Causal Part. Enter the word "Bulletin" in the Causal Part Description free-flow text field.

Version	1	
Modified	Released November 17, 2017	

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time	
7080498*	Add BRS Tape to Seat Tubes	0.3 hr	
*This is a unique Labor Operation for Pullatin use only			

*This is a unique Labor Operation for Bulletin use only.