

## **Service Bulletin**

File in Section:

Bulletin No.: 15-NA-047

Date: December, 2017

# **TECHNICAL**

Subject: Wobble Felt During Light Acceleration Between 19 km/h (12 mph) to 24 km/h (15 mph)

Attention: This Bulletin also applies to vehicles sold in Mexico.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Branu.	woder.	from	to	from	to		
Buick	Verano	2012	2017			All	All

Condition	Some customers may comment on a wobble felt during light acceleration between 19 km/h (12 mph) to 24 km/h (15 mph).
Cause	This condition may be due to generated axial force from the axle angle causing the powertrain to move side to side.

#### Correction

If you encounter a vehicle with the above concern, replace both the front wheel drive shafts and all one time use fasteners as required. Refer to *Front Wheel Drive Shaft Replacement - Left/Right Side* in SI.

#### **Parts Information**

Description	Part Number
SHAFT ASM-FRT WHL DRV	13335138
SHAFT ASM-FRT WHL DRV	13335139
One Time Use Fasteners	Refer to Parts Catalog

### **Warranty Information**

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3080158*	Both Front Wheel Drive Shafts Replacement	1.1 hrs
Add	Transmission Fluid Drain and Fill	0.7 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	3
Modified	March 14, 2016 – Updated Correction, Parts Information and Warranty Information.  December 19, 2017 – Added the 2017 Model Year and a Warranty statement.