

Service Bulletin

File in Section:

Bulletin No.: 17-NA-269

> Date: August, 2017

INFORMATION

Rear Camera Screen Bright at Night Subject:

Attention: This Bulletin replaces PIT5573.

Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
		from	to	from	to	Engine:	
Chevrolet	Silverado, Suburban, Tahoe	2017	2017				
GMC	Sierra, Yukon Models						

Involved Region or Country	North America and N.A. Export Regions	
Additional Options (RPOs)	Equipped with RADIO-INFOTAINMENT SYSTEM - UPLEVEL HMI, ENHANCED CONNECTIVITY and RADIO-INFOTAINMENT SYSTEM - UPLEVEL HMI, ENHANCED CONNECTIVITY, EMBEDDED NAVIGATION (RPOs IO5, IO6) WITHOUT RPO U42	
Condition	Some customers may comment that the rear camera display is too bright at night.	
Cause	This condition may be caused by a software anomaly.	
Correction	Updated software calibration has been released to address this condition. Reprogram the A22 Radio Controls with the latest software available.	

Service Procedure

Refer to Radio Control Programming and Setup in SI.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time	
2881278*	A22 Radio Control Reprogramming with SPS	0.3 hr	
*This is a unique Labor Operation for Bulletin use only.			

Version	1
Modified	