

1 03 08-17



## Service Information Bulletin

SUBJECT	DATE
SPN 3242 (ACM) (GHG17)	March 2017

### Additions, Revisions, or Updates

Publication Number / Title	Platform	Section Title	Change
DDC-SVC-MAN-0191	GHG17 Heavy Duty	SPN 3242/FMI 20 - GHG17	Updated diagnostics.

DiagnosticLink users: Please update the troubleshooting guides in DiagnosticLink with this newest version. To update the tool troubleshooting guide, open DiagnosticLink and from the Help – Troubleshooting Guides menu, select the appropriate troubleshooting manual, then click Update.



13400 Outer Drive, West, Detroit, Michigan 48239-4001  
Telephone: 313-592-5000  
[www.demanddetroit.com](http://www.demanddetroit.com)

## 2 SPN 3242/FMI 20 - GHG17

Diesel Oxidation Catalyst Temperature Drift - Inlet High or Outlet Low

**Table 1.**

SPN 3242/FMI 20	
Description	70°C (126°F) Difference During Non-regeneration Mode
Monitored Parameter	Diesel Oxidation Catalyst (DOC) Inlet Temperature vs. DOC Outlet Temperature
Typical Enabling Conditions	Coolant Temperature Greater than 60°C (140°F); Regen not Active in Last Five Minutes
Execution Frequency	Continuous When Enabling Conditions Met
Typical Duration	One Minute
Dash Lamps	MIL, CEL
Engine Reaction	Regen Inhibit and 10% Engine Derate
Verification	Low Temperature Regen



### WARNING: PERSONAL INJURY

Diesel engine exhaust and some of its constituents are known to the State of California to cause cancer, birth defects, and other reproductive harm.

- Always start and operate an engine in a well ventilated area.
- If operating an engine in an enclosed area, vent the exhaust to the outside.
- Do not modify or tamper with the exhaust system or emission control system.



### WARNING: PERSONAL INJURY

To avoid injury before starting and running the engine, ensure the vehicle is parked on a level surface, parking brake is set, and the wheels are blocked.



### WARNING: ENGINE EXHAUST

To avoid injury from inhaling engine exhaust, always operate the engine in a well-ventilated area. Engine exhaust is toxic.

Check as follows:

1. Check for multiple fault codes. Are SPN 3242/FMI 3, 4, 8 or SPN 3250/FMI 3, 4, and 8 present?
  - a. Yes; repair those faults first.
  - b. No; Go to step 2.



### WARNING: PERSONAL INJURY

Diesel engine exhaust and some of its constituents are known to the State of California to cause cancer, birth defects, and other reproductive harm.

- Always start and operate an engine in a well ventilated area.
- If operating an engine in an enclosed area, vent the exhaust to the outside.
- Do not modify or tamper with the exhaust system or emission control system.

**WARNING: PERSONAL INJURY**

To avoid injury before starting and running the engine, ensure the vehicle is parked on a level surface, parking brake is set, and the wheels are blocked.

**WARNING: ENGINE EXHAUST**

To avoid injury from inhaling engine exhaust, always operate the engine in a well-ventilated area. Engine exhaust is toxic.

2. Start the engine.
3. Run service routine Perform Performance Check - Low Temp ATD; allow the routine to run for 20 to 25 minutes.
4. Compare the Diesel Oxidation Catalyst (DOC) inlet temperature with DOC outlet temperature and Diesel Particulate Filter (DPF) outlet temperature. Are all three temperature sensors within 25°C (45°F) of each other?
  - a. Yes; DOC inlet and DOC outlet temperature sensors test good. Clear the code and release the vehicle.
  - b. No; Go to step 5.
5. Is the DOC outlet temperature sensor reading within 25°C (45°F) of the DPF outlet temperature sensor?
  - a. Yes; Go to step 8.
  - b. No; Go to step 6.
6. Shut OFF the engine.
7. Replace the DOC inlet temperature sensor.  
For 1-BOX™, Refer to section "Removal of the Diesel Oxidation Catalyst Inlet Temperature Sensor". Verify repair.  
For Two-BOX option, Refer to section "Removal of the Diesel Oxidation Catalyst Inlet Temperature Sensor". Verify repair.
8. Shut OFF the engine.
9. Replace the DOC outlet temperature sensor.  
For 1-BOX™, Refer to section "Removal of the Diesel Oxidation Catalyst Outlet Temperature Sensor". Verify repair.  
For Two-BOX option, Refer to section "Removal of the Diesel Oxidation Catalyst Outlet Temperature Sensor". Verify repair.