TECHNICAL INSTRUCTIONS

FOR

LIMITED SERVICE CAMPAIGN E03

U760 ATM ECM SOFTWARE UPDATE

CERTAIN 2012-2014 MY CAMRY


All dealership associates involved in the LSC process are required to successfully complete E-Learning course SC13A. To ensure that all vehicles have the repair performed correctly; technicians performing this LSC repair are required to currently hold <u>at least one</u> of the following certifications levels:

Toyota Certified (any classifications)

Toyota Expert (any classifications) Master

Master Diagnostic Technicians

I. OPERATION FLOW CHART



IDENTIFICATION OF AFFECTED VEHICLES

NOTE:

- □ Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this LSC and that the campaign has not already been completed prior to dealer shipment or by another dealer.
- □ TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected or was completed by another dealer.

II. PREPARATION

A. PARTS

Part Number	Part Description	Quantity					
00451-00001-LBL*	Authorized Modification Label	1		`			
*I abole can be ordered in packs of 25 from the MDC through the Dealer Daily Websit							

Labels can be ordered in packs of 25 from the MDC through the Dealer Daily Website

B. TOOLS, SUPPLIES & EQUIPMENT

- Standard Hand Tools
- Techstream 2.0 / TIS Techstream / Techstream Lite
- GR8 Battery Diagnostic Station
- T-SB-0034-14

III. BACKGROUND

Some 2012 – 2014 Camry vehicles equipped with a U760 transmission may intermittently exhibit a brief shudder, while driving under light loads at approximately 25 to 50 mph. The torque converter and Engine Control Module/ECM (SAE term: Powertrain Control Module/PCM) logic have been modified to reduce the possibility of this condition occurring.

IV. ECM CALIBRATION ID VERIFICATION AND DTC CHECK

A. CONFIRM ECM CALIBRATION ID

1) Perform a health check

STOP

2) Confirm the calibration ID in the ECM.

EMISSION SPEC	GRADE	ECM (CPU)	CALIBRATION	
			PREVIOUS	NEW
ULEV	Base, LE, XLE	Main	30679000	
			30679100	<u>30679400</u>
			30679200	<u>30073400</u>
			30679300	
		Sub	50611000	
			50611100 🖡 🦰	<u>50611400</u>
			50611200	
			50611300	
PZEV		Main	30680000	
			30680100	<u>30680400</u>
			30680200	
			30680300	
			50611000	<u>50611400</u>
		Sub 🎽	50611100	
			50611200	
			50611300	
ULEV	SE	Main	306A3000	
			306A3100	306A3400
			306A3200	
		Sub	306A3300	
			50612000	
			50612100	<u>50612400</u>
			50612200	
			50612300	
PZEV		Main	306A4000	<u>306A4400</u>
			306A4100	
			306A4200	
			306A4300	
	Sub		50612000	
		Sub	50612100	50612400
			50612200	
			50612300	

If the ECM has already been calibrated with the new calibration the campaign is complete.

V. ECM REFLASH PROCEDURE

A. CONNECT THE GR8

a) Set the GR8 to Power Supply Mode to help maintain 13.5 volts during ECM reprogramming.

A battery charger set to power supply mode *MUST* be used during reprogramming. ECM damage may occur if the correct battery charger setting is not used.

B. REFLASH THE ECM

a) Click yes on the health check results screen, or follow the links on the table above to begin the reflash process.

NOTE:


STOP

- For general reprogramming procedures, refer to T-SB-0012-13.
- Confirm the latest version of Techstream software is being used.

If the Techstream does not have sufficient battery power the reflash will fail.
Confirm the DLC3 cable is in good condition before attempting reflash.

C. ATTACH THE AUTHORIZED VEHICLE MODIFICATION LABEL

- a) Fill out the label.
- b) Affix the label to the under-side of the hood.



1. CHECK FOR DTCs

Note: This campaign only covers the ECM Reflash to reduce the possibility of a shudder condition occurring in the future.

◄ VERIFY REPAIR QUALITY ►

Confirm the ECM Calibration has been updated successfully Confirm *that an* Authorized Modification Label has been installed If you have any questions regarding this LSC, please contact your regional representative

VI. APPENDIX

A. CAMPAIGN DESIGNATION DECODER

