

March 2017 Technical Service

# CHECK CONTROL (CC) MESSAGE:"COOLANT LEVEL TOO LOW!" IS DISPLAYED

#### MODEL

G30 (5 Series Sedan)	G12 (7 Series Sedan)	
Coddii)	Coddin	

With the B46, B58 and XB1H (PHEV) engines up to February 2017

## SITUATION

CC message: "Coolant level too low!" appears in the display.

#### CAUSE

The cooling system wasn't efficiently bled during the factory fill.

# CORRECTION

Check the cooling system for leaks and repair and refill as necessary.

# **PROCEDURE**

1. Follow ISTA Repair Instruction **RA 17 00 009 Check coolant circuit for water tightness** (attached).

Were any coolant leaks discovered in the engine compartment?

YES- repair the leaks. Go to step 2.

NO - Go to step 3.

- 2. Refill and bleed the cooling system.
- 3. With a cold engine, fill the expansion tank to the full mark.

## WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	17 13 00 15 00	

Labor Operation:	Labor Allowance:	Description:
17 00 009*	Refer to KSD	Checking cooling system for leaks

Labor operation code 17 00 009 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 17 00 509 instead.

And

#### Sublet - Bulk Materials

Sublet Code 4	See sublet reimbursement calculation below	Reimbursement for replacing the drained quantity of antifreeze/coolant (Bulk container reference 82 14 1 467 704, one gallon container. Do not use this part number for claim submission)
---------------	--	---

Sublet calculation: BMW antifreeze/coolant (1 gallon bulk container reference P/N 82 14 1 467 704) for approximately 1 liter (2 liters total) that is needed for this repair (50/50 mixture) at dealer net plus your center's handling.

Enter this material cost in sublet and itemize the amount in the claim comment section.

# **ATTACHMENTS**

View PDF attachment RA 17 00 009 Check coolant circuit for watertightness.

[ Copyright ©2017 BMW of North America, Inc. ]