



## DYNAMIC STABILITY CONTROL FAILURE

### MODEL

G12 (7 Series)	G30 (5 Series Sedan)		
----------------	----------------------	--	--

Vehicles produced through March 10 2017.

### SITUATION

Instrument cluster indicates Dynamic Stability Control (DSC) failure.

You cannot establish communication with the DSC control unit.

Associated control units (DME, ACSM) register DSC-related communication time-outs.

After battery reset, DSC operates normally and has no faults registered.

### CAUSE

Software in the DSC control module.

### CORRECTION

Recode/reprogram the vehicle with ISTA NEXT 4.04.3 or higher

### PROCEDURE

For conditions that are similar to the situation described:

1. Perform diagnosis with the latest version of ISTA.
2. Program the vehicle using ISTA/P 3.61.2 or ISTA NEXT 4.04.3 or higher

<b>G12 (7 Series)</b>	Target integration level: S15A-17-03-505 or higher
<b>G30 (5 Series)</b>	

Note that ISTA/P will automatically reprogram and code all programmable control modules that do not have the latest software.

**Always connect a BMW approved battery charger/power supply ([SI B04 23 10](#)).**

For information on programming and coding with ISTA/P, refer to CenterNet / TIS / Technical Documentation / Diagnostics and Programming / Programming Documentation.

## PARTS INFORMATION

Part exchange does not provide a solution and is not approved.

## WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

<b>Defect Code:</b>	<b>3452101400</b>	
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 00 006	Refer to KSD2	Performing "vehicle test" (with vehicle diagnosis system – checking faults) (Main work)
Or:		
00 00 556	Refer to KSD2	Performing "vehicle test" (with vehicle diagnosis system – checking faults) (Plus work)
And, as necessary		
61 20 900	Refer to KSD2	Disconnecting and connecting battery earth lead (battery reset)
And:		
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply (indicated in KSD 2 as Charging battery)
And:		
61 00 730	Refer to KSD2	Programming/encoding control unit (s)

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowances.

### Vehicle Programming and Coding

When ISTA/P automatically reprograms and codes all the vehicle's control modules that "currently do not have" the latest software and if one or more control module failures occur "during" this programming procedure:

- Please claim this "consequential" control module-related repair work under the defect code listed in this bulletin with the applicable KSD2/AIR labor operations.

## Other Repairs

Control module failures that occurred “prior” to performing this programming procedure:

- When “covered” under an applicable limited warranty, claim this control module-related repair work using the applicable defect code and labor operations in KSD2/AIR.

[ Copyright ©2017 BMW of North America, Inc. ]