



SI B17 05 17
Cooling Systems

August 2017
Technical Service

SERVICE ACTION: REPLACE THE MOUNT FOR THE TRANSMISSION OIL COOLER THERMOSTAT

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

What's New:

- This Service Action repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement.

MODEL

G12 (7 Series)	G30 (5 Series)		
----------------	----------------	--	--

AFFECTED VEHICLES

This Service Action involves 5 and 7 Series produced June 7th and 8th 2017. Approximately 28 vehicles are affected by this Service Action. Refer to the attached VIN list.

Vehicles which require this Service Action to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

SITUATION

There may be a rattling noise coming from the engine area at the transmission oil cooler thermostat or (on xDrive models only) the transmission oil cooler lines coming into contact with the left front output shaft.

CAUSE

The bracket that holds the transmission oil cooler thermostat to the left front frame rail may be defective

CORRECTION

1. Replace the holder for the transmission oil cooler thermostat
2. On xDrive models: Check and if necessary, replace the transmission oil cooler lines and inner CV boot for the output shaft.

PROCEDURE

Remove the left front wheel as described in the repair instruction **REP 36 10 300 "Removing and installing the front or rear wheel"**.

Remove the stiffening plate as described in the repair instruction **REP 31 11 040 "Removing and installing/replacing the stiffening plate"**.


Remove the steering assembly cover as described in the repair instruction **REP 51 75 010 "Removing and installing/replacing the left or right steering assembly cover"**.

xDrive Vehicles only



- Inspect the cooler lines for contact with the left front output shaft (1). Replace the cooler lines if the CV boot has cut into the lines. Replace the inner CV boot if it is damaged (Reference Repair Instruction 31 60 535 "Replacing two gaiters on output shaft").

Note: The transmission cooler thermostat with holder is visible through the wheel well between the left front frame rail and the front sub-frame.



- Remove the two 8mm bolts (1) that hold the thermostat bracket to the sub-frame. Replace the bolts (PN 34 30 6 771 214) during installation and tighten to 8 Nm.

Note: The illustration shows the cooler lines removed for clarity and the bolts already loosened as a reference for the location of the bolts. **Do not remove the transmission cooler lines.**



- Disconnect the clamp holding the transmission oil cooler thermostat from the holder (1).



- Slide the holder out from the transmission oil cooler thermostat (1).

Install the new holder (PN 17 22 8 624 268) in reverse order.

Reinstall the steering assembly cover.

Reinstall the stiffening plate.

Reinstall the left front wheel.

PARTS INFORMATION

Less than 30 vehicles involved. Please monitor Parts Matrix DCS messages for parts ordering procedure.

Part Number	Description	Quantity
17 22 8 624 268	Replacement thermostat holder	1
34 30 6 771 214	Thermostat holder screw	2

Only if required:

Part Number	Description	Quantity
31 10 6 870 648*	Front underride protection hexagon screw	12
07 11 9 907 898*	Underride protection hexagon screw	2

WARRANTY INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the following information:

Defect Code:	0017790100	
Labor Operation:	Labor Allowance:	Description:
00 65 706	14 FRU	Replacement of the thermostat holder, visual inspection for damage (Plus work)
Or		
00 65 707	31 FRU (G12/G30 N63R); 32 FRU (G12 N74)	Replacement of the thermostat holder, visual inspection for damage and replacement of the inner axle boot (Plus work)
Or:		
00 65 708	55 FRU (G30); 65 FRU (G12 N63); 89 FRU (G12 N74)	Replacement of the thermostat holder, visual inspection for damage and replacement of the transmission oil cooler lines (Plus work)
Or:		
00 65 709	70 FRU (G30); 81 FRU (G12 N63); 104 FRU (G12 N74)	Replacement of old thermostat, visual inspection for damage and replacement of the axle boot and transmission oil cooler lines (Plus work)

And:

Sublet – Bulk Materials

Sublet Code 4	See sublet reimbursement calculation below	Reimbursement for the repair-related bulk materials (BMW part number(s), please do not use the part numbers for claim submission)
----------------------	--	---

Sublet reimbursement calculation for claiming the “used quantities” of repair-related bulk materials (BMW part numbers) is at dealer net plus your center’s handling.

Enter this material cost in sublet and itemize the amount on the repair order and in claim comment section.

And, as applicable:

Alternative Mobility Solutions (AMS) Reimbursement

This Service Action repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement, please claim this item under the Defect Code noted above as follows:

Sublet Code "2"	See below	Alternative Mobility Solution (AMS) expense reimbursement
-----------------	-----------	---

Claimable AMS-related reimbursement items and allowances (at cost, no markup)

- Mass transit (Up to \$15.00);
- Taxi and livery services (Up to \$15.00);
- "On-demand" Phone app-based transportation services (Up to \$15.00); or
- Vehicle pickup/drop off service "to and/or from" a customer's home or business location (Up to \$25.00).

Please refer to SI B01 29 16 for additional information. Itemize this sublet amount on the repair order and in the claim comment section.

Overlapping Labor Procedure – Other Repairs

If invoicing the KSD2 flat rate labor operation codes for other repair work results in overlapping labor, for those flat rate labor operations that are affected, you can now:

- Replace the stated KSD2 "FRU allowance" with a "reduced FRU value" to eliminate the overlapping labor.

For help in identifying the overlapping labor, please refer to the AIR FRU Plausibility Check (Overlapping Labor Tool) that is located in the AIR Client.

Eligible other repair work being claimed under a different defect code will require separate punch times.

On the repair order and in the claim comment section, please identify and itemize those labor operations being claimed with a "reduced FRU value."

ATTACHMENTS

View PDF attachment [B170517 VIN List](#).

[Copyright ©2017 BMW of North America, Inc.]

VIN (7)	Full VIN	Series	MY
B034863	WBAJB9C58JB034863	G30	2017
B034870	WBAJB9C55JB034870	G30	2017
GM23060	WBA7F0C52JGM23060	G12	2017
GM23056	WBA7F0C50JGM23056	G12	2017
GM23059	WBA7F0C56JGM23059	G12	2017
B034861	WBAJB9C54JB034861	G30	2017
G614644	WBA7H6C51JG614644	G12	2017
B034872	WBAJB9C59JB034872	G30	2017
B034871	WBAJB9C57JB034871	G30	2017
B034867	WBAJB9C55JB034867	G30	2017
B034868	WBAJB9C57JB034868	G30	2017
G424361	WBA7F2C55JG424361	G12	2017
G424358	WBA7F2C55JG424358	G12	2017
GM23062	WBA7F0C56JGM23062	G12	2017
GM23058	WBA7F0C54JGM23058	G12	2017
GM23063	WBA7F0C58JGM23063	G12	2017
GM23061	WBA7F0C54JGM23061	G12	2017
B034862	WBAJB9C56JB034862	G30	2017
B034864	WBAJB9C5XJB034864	G30	2017
G614645	WBA7H6C53JG614645	G12	2017
B034869	WBAJB9C59JB034869	G30	2017
B034865	WBAJB9C51JB034865	G30	2017
B034866	WBAJB9C53JB034866	G30	2017
B034873	WBAJB9C50JB034873	G30	2017
G424360	WBA7F2C53JG424360	G12	2017
G424362	WBA7F2C57JG424362	G12	2017
G856183	WBA7F2C58JG856183	G12	2017
GM23057	WBA7F0C52JGM23057	G12	2017