

Service Category	Vehicle Exterior		
Section	Door/Hatch	Market USA	Scion Supports ASE Certification

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION	
2016	iA		

Introduction

Some 2016 model year iA vehicles may exhibit a condition where the fuel door will NOT open due to a detached cable from the retainer when pulling the release lever. This condition may have been caused by incorrect assembly during manufacturing. Follow the procedure in this bulletin to address this condition.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
237991	R & R Retainer Fuel Filler Opening Lid Lock	0.5	77377-WB001	9A	57

this bulletin.

Parts Information

PART NUMBER	PART NAME	QTY
77377-WB001	Retainer, Fuel Filler Opening Lid Lock	1


Repair Procedure

1. Confirm operation of the interior fuel door release lever.

Is the lever inoperative and does NOT feel as if there is ANY tension on the lever when operating?

- YES Continue to step 2.
- **NO** If tension can be felt when pulling the fuel door release lever, then this bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
- 2. Open the fuel filler lid and remove the nut.






3. Remove the service hole cover on the trunk side trim (LH).

Figure 2.

1

Nut



Service Hole Cover


1



Repair Procedure (Continued)


4. Detach ALL the stopper bracket tabs from the body and remove the stopper bracket.

Figure 3.



5. Remove the fuel filler lid opener in the direction of the arrow.





Fuel Filler Lid Opener

1

Repair Procedure (Continued)

6. Rotate the fuel lid opener 180 degrees to the right and reinstall.

NOTE

The open side will face the inboard side of the vehicle.

- 7. Connect the fuel lid lock control cable assembly.
- 8. Attach ALL the stopper bracket tabs.
- 9. Install the service hole cover.
- 10. Install the nut.

Torque: 4.5 N*m (46 kgf*cm, 40 in*lbf)

11. Confirm repair and proper operation.

Figure 5.

