



Technical Service Bulletin

19 Heating output insufficient (DTC B10D004 and/or B11D501)

19 17 90 2047114/4 September 12, 2017. Supersedes Technical Service Bulletin Group 19 number 17-85 dated April 4, 2017 for reasons listed below.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|------------------|-------------|-----------|----------------------------|
| A6, A7 | 2012 - 2015 | All | Not Applicable |
| S6, S7, and RS 7 | 2015 | All | Not Applicable |
| A8, S8 | 2014 - 2017 | All | Not Applicable |
| S8 + | 2016 -2017 | All | Not Applicable |

Condition

| REVISION HISTORY | | |
|------------------|------------|---|
| Revision | Date | Purpose |
| 4 | - | Revised <i>Warranty</i> (Updated Labor Operations and Service Number) |
| 3 | 04/06/2017 | Revised header data (Added model years) Revised <i>Warranty</i> (Updated Labor Operations) |
| 2 | 03/15/2017 | Revised <i>Warranty</i> (Updated Labor Operations) |

Customer statement:

- Insufficient heating output
- Passenger compartment does not get warm

Workshop findings:

The customer statement can be reproduced. In the climatronic control module, J255 (address word 0008), at least one of the following DTC(s) is logged:

- **DTC B10D004** (coolant circulation pump, mechanical fault)

Or

- **DTC B11D501** (supply voltage of terminal 30 for coolant circulation pump, electric fault)

Technical Background

The V50 coolant recirculation pump is malfunctioning.



Technical Service Bulletin

Production Solution

Improved coolant pump.

Service

Replace the V50 coolant recirculation pump, use the washers if pump is mounted with screws to the bracket as shown (some models have rubber covered metal band instead):

- N 011 523 21 (3x)




Figure 1. Washers installed.

To ensure about 1mm distance between the V50 coolant recirculation pump and its bracket (Figure 1 and 2):

Bleed the coolant circuit according to ElsaPro at *Repair Manual >> Engine >> 19 Cooling System >> Cooling System/Coolant >> Cooling, Draining and Filling.*



Figure 2. Pump mounted.



Technical Service Bulletin

Warranty

| | | | |
|--------------------------|---|--------------|--|
| Claim Type: | <ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If vehicle is outside any warranty, this Technical Service Bulletin is informational only. | | |
| Service Number: | 1947 | | |
| Damage Code: | 0010 | | |
| Labor Operations: | A6, S6, A7, S7, RS 7 | | |
| | Additional coolant pump remove + reinstall (V50) | 1947 1950 | 70 TU |
| | Cover (plenum) remove + reinstall | 8522 1900 | 20 TU |
| | A8, S8 | | |
| | Additional coolant pump remove + reinstall (V50) | 1947 9999 | 30 TU |
| | Cover (plenum) remove + reinstall | 8522 1900 | 70 TU |
| Diagnostic Time: | GFF | 1500 0000 | Time stated on diagnostic protocol (Max 20 TU) |
| | Road test prior to service procedure | No allowance | 0 TU |
| | Road test after service procedure | 0121 0004 | 10 TU |
| | Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details) | | |
| Claim Comment: | As per TSB #2047114/4 | | |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Required Parts and Tools

| Part Number | Part Description | Quantity |
|--------------|--------------------------------|----------|
| 06D 121 601 | V50 coolant recirculation pump | 1 |
| N 906 87 001 | Spring clips 27 x12 | 2 |
| N 011 523 21 | Washer 5 x10 x 1 | 3 |
| G 013A8J1G | Coolant additive | 1 |

| Tool Number | Tool Description |
|-------------|------------------------------|
| VAS6096 | Cooling System Charging Unit |
| VAG 1974/8 | Adapter |
| VAG 1978/17 | Adapter |

Additional Information

All parts and service references provided in this TSB (2047114) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.