

# Service Update

## 17309 Diesel Particulate Filter Soot Model DTC Disabled



Reference Number: N172114810

Release Date: August 2017

Revision: 00

**Attention:** This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

Make	Model	Model Year		RPO	Description
		From	To		
Chevrolet	Silverado HD	2018	2018	L5P	Duramax Diesel Engine
GMC	Sierra HD	2018	2018		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

<b>Condition</b>	On certain 2018 model year Chevrolet Silverado HD and GMC Sierra HD vehicles equipped with a Duramax diesel engine (RPO L5P), DTC P2002 may be disabled causing a cracked or inoperative diesel particulate filter to go undetected. The customer may see black smoke exiting the tail pipe.
<b>Correction</b>	Dealers are to reprogram the engine control module.

### Parts

No parts are required for this procedure.

### Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9102932*	Engine Control Module Reprogramming with SPS	0.3	ZFAT	N/A
9103375**	Module Programming Not Required	0.2	ZFAT	N/A

\*To avoid warranty transaction rejections, the SPS Warranty Claim Code must be entered when submitting this transaction.

\*\* SPS Warranty Claim Code is NOT required when submitting this transaction.

### Service Procedure

**Note:** Carefully read and follow the instructions below.

- DO NOT attempt to order the calibration number from GM Customer Care and Aftersales. The calibration numbers required for this service procedure are programmed into control modules via a Multiple Diagnostic Interface (MDI) with the calibration update. If you cannot access the calibration, call the Techline Customer Support Center and it will be provided.
- DO NOT program a control module unless directed to by a service procedure or a service bulletin. If the control module is not properly configured with the correct calibration software, the control module will not control all of the vehicle features properly.
- Ensure the programming tool is equipped with the latest software and is securely connected to the data link connector. If there is an interruption during programming, programming failure or control module damage may occur.
- Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. When required install the *EL-49642* SPS Programming Support Tool to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.
- Turn OFF or disable systems that may put a load on the vehicles battery such as; interior lights, exterior lights (including daytime running lights), HVAC, radio, etc.
- During the programming procedure, follow the SPS prompts for the correct ignition switch position.
- Clear DTCs after programming is complete. Clearing powertrain DTCs will set the Inspection/Maintenance (I/M) system status indicators to NO.
- Refer to *K20 Engine Control Module: Programming and Setup* for additional information on programming.

## Service Update

### 17309 Diesel Particulate Filter Soot Model DTC Disabled



**Note:** If the Same Calibration/Software Warning is noted on the SPS Controller screen, do NOT attempt to program the module. No further action is required. Refer to the Warranty section of the bulletin and use labor operation code 9103375, Module Programming Not Required.

1. Reprogram the engine control module. Refer to *K20 Engine Control Module: Programming and Setup* in SI.
2. Record SPS Warranty Claim Code on job card for warranty transaction submission.

#### Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.



GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS4538  
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 23, 2017

Subject: 17309 - Service Update  
Diesel Particulate Filter Soot Model DTC Disabled

Models: 2018 Chevrolet Silverado HD  
2018 GMC Sierra HD  
Equipped with Duramax Diesel Engine (RPO L5P)

To: All General Motors Dealers

General Motors is releasing Service Update 17309 today. The total number of U.S. vehicles involved is 33. Please see the attached bulletin for details.

**Global Warranty Management (GWM)**

The Investigate Vehicle History (IVH) screen in the GWM system will be updated August 24, 2017. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until the VIN appears in IVH.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS