

# **Technical Tip**

Topic	96-10-11TT – Reader Coil Test for Key Not Being Read and Fault 01128		
Market area	United States 444 Volkswagen of America, Inc. (6444)		
Brand	Volkswagen		
Date	September 19, 2017		

## Condition

#### **ATTENTION:**

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

### Reader Coil Test for Key Not Being Read and Fault 01128

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	1999-2005	All	All	All	All

# **Technical Background**

NA.

#### **Service**

To test the reader coil, begin by back probing one wire at the reader coil with the red DVOM test lead and ground the other meter test lead. Switch the ignition key ON and check the reading. The reading should be more than 80mV and then decline to ~70mV. A fault in the system will show less than ~20mV.

Regardless of initial reading, gently remove the cluster (leave wiring attached) with ignition key ON. Monitor the voltage reading while wiggling the green cluster connector. If the reading fluctuates between ~70mV and ~20mV the cause may be a poor contact at the cluster connector.

Replace the two reader coil wire terminals and retest. If there is no voltage when switching the key to the ON position, the immobilizer should be replaced. If the reading remains at ~20mV, test the reader coil resistance. Reader coil resistance should read between 18 and 24 ohms.

# **Additional Information**

Revision History					
Revision Number	Released Date	Reason For Update			
2031508/3	9/19/17	Update to latest standard.			
2031508/2	2/21/14	Update to information.			
2031508/1	12/3/10	Original publication.			

© 2017 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

1