

Wind or airflow noises in area of doors

Topic number	LI72.10-P-062500
Version	9
Function group	72.10 Front door
Date	10-20-2017
Validity	MODEL 205.0/1/2; 253
Reason for change	Part numbers for MODEL 205.0/1/2 updated.
Reason for block	

Complaint:

Wind or airflow noises in the area of the doors.

Cause:

Airflow noises, tire noise.

The noises entering the interior are perceived to be too loud.

Remedy:

MODEL 205

1. Check door adjustment. Also check the transition from the doors to the A-pillar, see Figure 1, and correct if necessary by adjusting the doors in the y-direction.
2. Check outside mirror cover for parallelism and correct seating, see Figure 2, and adjust if necessary.
3. Check rib on mirror triangle seal for kinks as per arrows, see Figure 3, and replace if necessary.
4. Cut insulation to a length of 30 mm and attach to waistline trim strip at front on left and right according to the circles, see Figure 3 and Figure 4.
5. Perform a test drive. If the noise level is unchanged, continue with step 6.

MODEL 205, 253

6. Using suitable adhesive tape, cover the joints in the area of the front doors, outside mirrors, windshield and engine hood, see example in Figure 5, Figure 6 and Figure 7. Perform a test drive.
7. If the noise level is unchanged, install front side windows with code 851 (Acoustics package).

Note: Document conversion of front side windows in VeDoc in FO Texts field.

Attachments	
File	Description
Bild 1.JPG	Picture 1
Bild 2.JPG	Picture 2
Bild 3.JPG	Picture 3
Bild 5.JPG	Picture 5
Bild 6.JPG	Picture 6
Bild 7.JPG	Picture 7
Bild 4.JPG	Picture 4

XENTRY TIPS

Symptoms

Body / Door/Flap / Door / Door / Wind noises

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 205 725 23 00			Left door side window	1	MODEL 205.0/1/2: Up to production date: F 02.08.2016	X
A 205 725 18 00			Right door side window	1	MODEL 205.0/1/2: Up to production date: F 02.08.2016	X
A 205 737 21 00			Insulation	2		X
A 253 725 59 00			Left door side window	1	MODEL 253.9: Up to production date: L 31.01.2016 (CKD) Up to production date: F 30.01.2016	X
A 253 725 60 00			Right door side window	1	MODEL 253.9: Up to production date: L 31.01.2016 (CKD) Up to production date: F 30.01.2016	X
A 253 725 83 00			Left door side window	1	MODEL 253.9: As of production date: L 31.01.2016 (CKD) As of production date: F 30.01.2016	X
A 253 725 84 00			Right door side window	1	MODEL: 253.9 As of production date: L 31.01.2016 (CKD) As of production date: F 30.01.2016	X
A 253 725 62 00			Left door side window	1	MODEL: 253.3	X
A 253 725 63 00			Right door side window	1	MODEL: 253.3	X
A 205 725 63 00			Left door side window	1	205.0/1/2: As of production date: F 02.08.2016	X
A 205 725 64 00			Right door side window	1	205.0/1/2: As of production date: F 02.08.2016	X

Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
			72A01 39	
			72N01 39	

WIS-References

Document number	Title	Note	Allocation
-----------------	-------	------	------------

XENTRY TIPS

AR72.10-P-1900LW	Remove/install crank window in front door		Remedy
------------------	---	--	--------

Attachments

Bild 1.JPG:



Bild 2.JPG:



XENTRY TIPS

Bild 3.JPG:




Bild 5.JPG:



XENTRY TIPS

Bild 6.JPG:



Bild 7.JPG:



XENTRY TIPS

Bild 4.JPG:

