

Service Bulletin

File in Section:

Bulletin No.: 17-NA-298

Date: September, 2017

TECHNICAL

Subject: Headliner Sag

Brand:		Model:	Model Year:		VIN:		Engine:	Transmission:
	Branu.	woder.	from	to	from	to		
	Chevrolet	Camaro Coupe	2016	2018			All	All

Involved Region or Country	North America, South America, China, Europe, Republic of Korea, Puerto Rico, Russian Federation, Middle East, U.S. Virgin Islands, Israel, Japan, North Africa		
Condition 1	486356		
	Some customers may comment on seeing the headliner sagging above the passenger door. The graphic above shows a view from outside the passenger door.		
Cause 1	The cause of the condition may be that the Roof Rail Air Bag (RRAB) connector is not allowing the headliner to lay flat in this area.		

Copyright 2017 General Motors LLC. All Rights Reserved.

Condition 2



Bulletin No.: 17-NA-298

passenger side visor. The graphic above shows a view from inside the vehicle, looking upward at the upper corner of the windshield.

Cause 2 The cause of the condition may be mishandling of the headliner during installation. If either condition is evident, replace the headliner. Refer to Headlining Trim Panel Replacement in SI. Correction Important: Caution should be taken during installation not to cause damage to the replacement headliner. Also ensure the RRAB connector routing issue is eliminated.

Parts Information

Use the vehicle identification number (VIN), SI, and the GM Electronic Parts Catalog to determine the proper part to order.

Causal Part	Description	Part Number	Qty
X	PANEL ASM- HDLNG TR	Various	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
1020210	Headlining Trim Panel Replacement	Use Published Labor Operation Time

Version	1
Modified	Released September 19, 2017