VOLVO CAR SERVICE AND PARTS BUSINESS



Technical Journal

TITLE: Front seat back uneven, lumbar support loose

REF NO:	ISSUING DEPARTMENT:	CAR MARKET:		
TJ 30962.2.0	Technical Service	United States and Canada		
3 US 7	PARTNER:	ISSUE DATE:	STATUS DATE:	
	7510 Volvo Car USA	2017-09-11	2017-09-12	
FUNC GROUP: 8524	FUNC DESC: Backrest cushion	Page ⁻	1 of 10	

"Right first time in Time"

Attachment

File Name	File Size
Example.pdf	0.2249 MB
TJ 30962.pdf	3.7335 MB

Vehicle Type

Туре	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256						2016-2016		0000561-0154064	201505-201646

CSC Customer Symptom Codes

Code	Description
S1	Seat upholstery/padding/Loose, poor fit, warped, wrinkled or soft/hard

VST Operation Number

VST Operation Number	Description
98561-2	Lumbar support adjust acc. to TJ30962

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste. © 2017 VOLVO CAR USA, LLC



Text

DESCRIPTION:

* Attachment "Example pdf" show typical wrinkle on the back support when the lumbar support is loose.

If a front seat back looks uneven when the lumbar support is used, the lumbar support may be loose.

SERVICE:

Use strip clamp 983750 to fasten the steel reinforcement in the foam to the hooks. Do this on both front seats. Follow attached repair method.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8524.

To view TJ attachment continue to next page. This TJ has two attachments.



Technical Journal 30962.2.0



VOLVO	/olvo Car Customer Service	TJ 30962	
Title	Front seat	Page	1(7)
Action	Product fix	Operation number:	98561-2
Issue Date	Reason		

Affected vehicles

2015-12

First issue

1

 Model year
 Model


 2016
 XC90 (16-)

Materials				
Materials	Qty.	Part No.	Notes	
Strip clamp	4.0	983750		

Removal


Note! Removal steps in this procedure may contain installation details.

Orientation view




Page 3 (7)


Image philosophy




On both sides.









Note! The graphic shows the back of the component before removal.






On both sides. Remove the marked part.







Installation

To install, reverse the removal procedure.