# Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Su	b	ie	ct	:
		J-		-

MAZDA CONNECT TOUCH SCREEN DOES NOT WORK OR OPERATES BY ITSELF Bulletin No.: 09-043/17

Last Issued: 11/09/2017

### APPLICABLE MODEL(S)/VINS

2014-2016 Mazda3 (Japan and Mexico built)

# DESCRIPTION

Some customers may experience a MAZDA CONNECT touch panel that does not accept touch commands properly or operates by itself. This is caused by a touch panel failure from an improper manufacturing process of the touch panel and center display integration.

# **REPAIR PROCEDURE**

1. Verify customer concern.

2. Remove the center display according to the instructions on MGSS "CENTER DISPLAY REMOVAL /INSTALLATION".

3. Look at the label at the bottom of the center display and check the first two letters of the lot number.

	BHP1 61 1J00 DISPLAY-INFORMATION IFONYF-14500-45 1 K4000 4007J
3397a	

- If the lot number starts with 6K or lower (3, 4, 5, 6A, 6B,....6J, 6K), go to the next step.
- If the lot number starts with 6L or higher (6L, 7,...), the concern is more likely caused by a different issue. Follow the instructions on MGSS for further diagnosis. If nothing is found, go to the next step.

4. Replace the center display with a new one.

5. Verify repair.

#### Page 1 of 2

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

## PARTS INFORMATION

Parts Number	Description	Qty.
BHP1-61-1JOD	Display, Information	1

# WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	А
Symptom Code	64
Damage Code	9W
Part Number Main Cause	BHP1-61-1JOD
Quantity	1
Operation Number / Labor Hours:	XXN98XRX / 0.3 Hrs.

Page 2 of 2

**CONSUMER NOTICE**: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.