ISM73622 Discovery Sport / L550 5 MY - InControl Touch - Clock errors in the Touch Screen Display Electrical 3-Nov-2017 00:00:00 04000 Instrumentation SSUE: after completing Q634 or Q627, the customer may report the clock is not displayed in the touchscreen, or freezes after start up, or displays a different time to that in the instrument display. Sause: acoftware update required action: In the interim carry out the following procedure . CAUTION: This procedure requires DVD151.04 and Calibration File 282 loaded or a
5 MY - InControl Touch - Clock errors in the Touch Screen Display Electrical 3-Nov-2017 00:00:00 04000 Instrumentation <u>SSUE:</u> Ifter completing Q634 or Q627, the customer may report the clock is not displayed in the touchscreen, or freezes after start up, or displays a different time to that in the instrument display. <u>Sause:</u> Software update required action: In the interim carry out the following procedure
Electrical 3-Nov-2017 00:00:00 04000 Instrumentation ssue: after completing Q634 or Q627, the customer may report the clock is not displayed in the touchscreen, or freezes after start up, or displays a different time to that in the instrument display. Sause: coftware update required action: in the interim carry out the following procedure
3-Nov-2017 00:00:00 04000 Instrumentation <u>Ssue:</u> After completing Q634 or Q627, the customer may report the clock is not displayed in the touchscreen, or freezes after start up, or displays a different time to that in the instrument display. <u>Sause:</u> Software update required <u>Action:</u> In the interim carry out the following procedure
04000 Instrumentation  SSUE:  After completing Q634 or Q627, the customer may report the clock is not displayed in the touchscreen, or freezes after start up, or displays a different time to that in the the instrument display.  Sause: Software update required  Action: The interim carry out the following procedure
After completing Q634 or Q627, the customer may report the clock is not displayed in the touchscreen, or freezes after start up, or displays a different time to that in the instrument display.
After completing Q634 or Q627, the customer may report the clock is not displayed in the touchscreen, or freezes after start up, or displays a different time to that in the instrument display. Cause: Coftware update required Action: In the interim carry out the following procedure
coftware update required <u>action:</u> In the interim carry out the following procedure
n the interim carry out the following procedure
CAUTION: This procedure requires DVD151.04 and Calibration File 282 loaded or
<ul> <li>Accornect the Jaguar Land Rover approved battery support unit.</li> <li>Connect the Jaguar Land Rover approved battery support unit.</li> <li>Connect the Jaguar Land Rover approved diagnostic equipment to the vehicle.</li> <li>Begin a new diagnostic session by reading the Vehicle Identification Number (VIN) or the current vehicle and initiating the data collect sequence.</li> <li>Follow the Jaguar Land Rover approved diagnostic tool prompts</li> <li>Select 'Diagnosis' session type.</li> <li>Select the following symptoms: Electrical - Information and entertainment system - intertainment system.</li> <li>Run and close the 'Datalogger' tool to reveal the 'Extras' tab.</li> <li>Select the 'Extras' tab.</li> <li>Form 'Recommendations', run 'Configure existing module – Audio head unit - Low ne'.</li> <li>When all of the tasks are complete, exit the current session by selecting the Session' tab and then select the 'Close Session' option.</li> <li>Disconnect the Jaguar Land Rover approved diagnostic equipment and the Jagua and Rover approved battery support unit.</li> </ul>

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.