

LTB00823NAS2



TECHNICAL BULLETIN

28 NOV 2017

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

Changes are highlighted in blue

SECTION:

204-01: Front Suspension

SUBJECT/CONCERN:

'Creak' Noise From Stabilizer Bar Bushing-Front

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Range Rover Evoque (LV)	2012	000447-000695	Halewood
Range Rover Evoque (LV)	2012-2015	600018-999999	Halewood
Range Rover Evoque (LV)	2015 Onwards	000051 Onwards	Halewood

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

A ' creak' noise from the front suspension stabilizer bar bushing(s) may be evident at lower ambient temperatures.

CAUSE:

This may be caused by 'stick/slip' between the stabilizer bar bushing and the stabilizer bar.

ACTION:

Should a customer express this concern, follow the Workshop Procedure below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY
LR110708	Front Stabilizer Bar Bushing	2
FX110056	M10 nut - Front stabilizer bar-to-drop link	2
LR024150	M14 x 85 bolt - Front suspension lower arm-to-front subframe	4

PART NUMBER	DESCRIPTION	QUANTITY
FY114056	M14 nut - Front suspension lower arm-to-front subframe	4

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Bush - Stabilizer bar - Front - Pair - Renew	60.10.05	0.3	41	LR079950
Front wheel alignment - Check and adjust	57.65.01.01	0.7	41	LR079950

NOTE:

Normal Warranty procedures apply.

WORKSHOP PROCEDURE:

1


CAUTION:



Lubricant must NOT be used when installing the new stabilizer bar bushing-front.

NOTE:

The new stabilizer bar bushing-front can be identified by a YELLOW painted dot in the area shown.



E182199

Install new stabilizer bar bushings-front (see TOPIx Workshop Manual section 204-01: Front Suspension - Front Stabilizer Bar Bushing).

-
- 2 Check and adjust the front wheel alignment (see TOPIx Workshop Manual section 204-00: General Information - General Procedures - Four Wheel Alignment).