# LTB00590NAS3 TECHNICAL BULLETIN 31 OCT 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

#### INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

# Changes are highlighted in blue

## SECTION:

412-01A: Climate Control

SUBJECT/CONCERN:

#### Climate Control System Odor

# AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	

#### LTB00590NAS3 - Climate Control System Odor | TOPIx

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Range Rover Sport (LW)	2014	300000-321100	Solihull
Range Rover (LG)	2013-2014	001204-140400	Solihull

MARKETS:

# NORTH AMERICA

# CONDITION SUMMARY:

SITUATION:

An odor may be present when the Climate Control System is switched 'ON'.

CAUSE:

This may be caused by mold spore accumulation / build-up in the front evaporator core.

#### ACTION:

Should a customer this express concern, follow the Workshop Procedure below.

# PARTS:

PART NUMBER	DESCRIPTION	QUANTITY:	
LR056368	Evaporator	1	
LR055993	Particle Filter	1	

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

## NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Evaporator core - Renew - Range Rover Sport (L494)	82.25.20	6.6	42	LR036365
Filter - Fresh air intake - Renew - Range Rover Sport (L494)	80.15.42	0.1	42	LR036365
Evaporator core - Renew - Range Rover (L405)	82.25.20	7.1	42	LR036365
Filter - Fresh air intake - Renew - Range Rover (L405)	80.15.42	0.1	42	LR036365

## NOTE:

Normal Warranty procedures apply.

WORKSHOP PROCEDURE:

1

# NOTE:

Prior to installation, wash out the evaporator core housing with warm water to remove any mold spore accumulation.

Replace the front evaporator (see TOPIx Workshop Manual section 412-01A: Climate Control).

<sup>2</sup> Replace the particle filter (see TOPIx Workshop Manual section 412-01A: Climate Control).