



LTB01090NAS1

# TECHNICAL BULLETIN

12 OCT 2017

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

## INFORMATION

---

## SECTION:

211-05: Steering Column Multifunction Switch

## SUBJECT/CONCERN:

Indicator / Wiper Stalks Inoperative or Intermittent Function

## AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Discovery Sport (LC)	2015 Onwards	500006 Onwards	Halewood
Discovery (LR)	2017 Onwards	000001 Onwards	Solihull
Range Rover Evoque (LV)	2012	000447-000695	Halewood

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Range Rover Evoque (LV)	2012-2015	600018-999999	Halewood
Range Rover Evoque (LV)	2015 Onwards	000051 Onwards	Halewood
Range Rover Sport (LW)	2014	001154-001205	Solihull
Range Rover Sport (LW)	2014-2015	300003-399997	Solihull
Range Rover Sport (LW)	2014-2016	500023-599874	Solihull
Range Rover Sport (LW)	2015 Onwards	600188 Onwards	Solihull
Range Rover Sport (LW)	2016 Onwards	100369 Onwards	Solihull
Range Rover (LG)	2013 Onwards	000010 Onwards	Solihull

---

## MARKETS:

NORTH AMERICA

---

## CONDITION SUMMARY:

### SITUATION:

The lighting control switch and/or the wiper control switch may not operate or operates intermittently.

### CAUSE:

This may be caused by a poor electrical connection at the lighting control switch and/or the wiper control switch.

### ACTION:

Should a customer express concern, follow the Workshop Procedure below.

---

## PARTS:

### NOTE:

One (1) tube of Nyogel electrical lubricant sufficient for 10 vehicles.

PART NUMBER	DESCRIPTION	QUANTITY:
LR054614	Nyogel electrical lubricant	1

---

**TOOLS:**

Refer to Workshop Manual for any required special tools.

---

**WARRANTY:**
**NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Lighting and wiper control switches - Apply Nyogel - Discovery Sport (L550), Discovery (L462), Range Rover Evoque (L538)	86.65.89.38	0.3	42	LR024629
Lighting and wiper control switches - Apply Nyogel - Range Rover (L494), Range Rover (L405)	86.65.89.38	0.2	42	LR024629

**NOTE:**

Normal Warranty procedures apply.

---

**WORKSHOP PROCEDURE:**

1

**NOTE:**

The lighting control switch/wiper control switch may also be referred to as steering column multifunction switch.


Remove the lighting control switch (see TOPIx Workshop Manual section 211-05: Steering Column Multifunction Switch).

- Reconnect and disconnect the lighting control switch twice to clean the electrical contact points.

2

### NOTES:

- Do not apply Nyogel to the lighting control switch connector.
- Make sure there is an even coating of Nyogel on the electrical contacts surface.
- Remove any excess Nyogel.



With the lighting control switch removed, apply the Nyogel to the electrical contacts surface.

- 3 Repeat steps 1-2 for the wiper control switch.

- 4 To install, reverse the removal procedure.