



NUMBER: 18-024-17 REV. A

GROUP: Vehicle Performance

DATE: March 31, 2017

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 18-024-17 MARCH 03, 2017, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDE ADDING A DIAGNOSTIC TROUBLE CODE (DTC) FOR 5.7L ENGINES, UPDATED BUILD DATE, LOP AND FAILURE CODE.**

FOR HELP WITH USING wiTECH FOR ECU FLASH REPROGRAMMING, CLICK ON THE APPLICATION'S "HELP" TAB.

THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.

SUBJECT:

Flash: Powertrain Diagnostic And System Enhancements

OVERVIEW:

This bulletin involves reprogramming the Powertrain Control Module (PCM) with the latest available software.

MODELS:

2016 - 2017 (WK)	Jeep Grand Cherokee
2016 - 2017 (WD)	Dodge Durango

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA, LATAM, APAC and EMEA.

NOTE: This bulletin applies to WK, WD vehicles built on or after March 30, 2016 (MDH 0330XX) and on or before **March 06, 2017 (MDH 0306XX)**** equipped with 5.7L V8 MDS VVT ENGINE (Sales Code EZH).**

NOTE: This bulletin applies to WK vehicles built on or after March 14, 2016 (MDH 0314XX) and on or before January 25, 2017 (MDH 0125XX) equipped with 3.6L V6 24V VVT Engine I W/ESS (Sales Codes ERC).

NOTE: This bulletin applies to WD vehicles built on or after March 30, 2016 (MDH 0330XX) and on or before January 25, 2017 (MDH 0125XX) equipped with 3.6L V6 24V VVT Engine I W/ESS (Sales Codes ERC).

NOTE: This bulletin applies to WK vehicles built on or after March 30, 2016 (MDH 0330XX) and on or before January 25, 2017 (MDH 0125XX) equipped with 3.0L V6 24V VVT Engine I W/ESS (Sales Codes EHW).

SYMPTOM/CONDITION:

A small number of customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find the following DTCs set in the PCM memory:

- ****U1424 - Implausible Engine Torque Signal Received (2017 MY Only)**.**
- P2681 - Engine Coolant Bypass Valve Control Circuit Open (3.6L Only).
- P0335 - Crankshaft Position Sensor Circuit.
- P2299-00 - Brake Pedal Position/Accelerator Pedal Position Incompatible.
- B23C3 - Stop/Start Disable Switch 1/2 Correlation (3.0L and 3.6L Only).

In addition, customers may experience the following conditions:

- A shorter auxiliary battery life.
- An illuminated Automatic Oil Change Indication (AOCI) light (3.6L Only).

Other enhancements included in this update:

- Improved knock sensor performance.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

- 3. Verify the Transmission Control Module (TCM) is programmed with the latest available software. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the TCM software.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
** 18-19-06-QV**	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	1- Engine Repair and Performance	0.2 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 5 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

****The dealer must use failure code CC with this Service Bulletin.**

- If the customer’s concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C’s (customer’s concern, cause and correction) must be provided for processing Service Bulletin flash/reprogramming conditions.**

CC	Customer Concern
----	------------------