



NUMBER: 09-005-17 REV. A

GROUP: 09 - Engine

DATE: August 3, 2017

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 09-005-17, DATED JULY 26, 2017, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDE REVISED RRT STATEMENT IN DIAGNOSIS.**

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 17-068. ALL APPLICABLE SOLD AND UNSOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

2.0L Coolant Hose O-Ring Replacement

OVERVIEW:

This bulletin involves replacing the O-ring on the turbocharger coolant hose.

MODELS:

2017

(GA)

Alfa Romeo Giulia

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA.

NOTE: This bulletin applies to vehicles built on or before January 13, 2017 (MDH 0113XX) equipped with a 2.0L 280HP I4 DI Turbo Engine (Sales Code EC2).

SYMPTOM/CONDITION:

The customer may experience a small coolant leak from the O-ring seal of the turbocharger coolant hose.

DIAGNOSIS:

****If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. If any vehicle not on the VIN list exhibits the symptom/condition, perform the repair.****

PARTS REQUIRED:

Qty.	Part No.	Description
1	68338389AA	O-ring
(AR)	68163848AB	Coolant

REPAIR PROCEDURE:

1. Remove the coolant hose from the turbocharger (Fig. 1) . Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: 09 - Engine, 2.0L/ Turbocharger System/Lines, Tubes and Hoses, Turbocharger, Oil and Coolant/Removal.




Fig. 1
Turbocharger Coolant Hose

1 - Turbocharger Coolant Hose (Shown with bolt removed)

-
2. Replace the O-ring attached to the end of the coolant hose (Fig. 2) with the new one listed in Parts Required.




Fig. 2
Turbocharger Coolant Hose O-rings

1 - Bad O-ring (Black)
2 - Good O-ring (Orange)

-
3. Re-install the coolant hose to the turbocharger. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: 09 - Engine, 2.0L/Turbocharger System/Lines, Tubes and Hoses, Turbocharger, Oil and Coolant/Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
07-70-01-90	O-ring, Coolant Return Tube from Turbocharger - Replace (1 - Semi-skilled)	1 - Engine Repair And Performance	1.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------