



**NUMBER:** 08-044-17 REV. B

**GROUP:** 08 - Electrical

**DATE:** August 5, 2017

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THIS BULLETIN SUPERSEDES SERVICE BULLETIN 08-044-17 REV. A, DATED JUNE 17, 2017, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **\*\*ASTERISKS\*\*** AND INCLUDE NEW RAPID RESPONSE TRANSMITTAL (RRT) NUMBER, ADDITIONAL DIAGNOSTIC TROUBLE CODE (DTCs), BUILD DATE, ADDED STEPS, UPDATED NOTES, ADDED INSPECTION LOP AND NEW LOP.**

**THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RRT **\*\*17-074\*\***. ALL APPLICABLE SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.**

**FOR HELP WITH USING wiTECH FOR ECU FLASH REPROGRAMMING, CLICK ON THE APPLICATION'S "HELP" TAB.**

**THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.**

***SUBJECT:***

Flash: Hybrid Control Processor (HCP) and the Auxiliary Hybrid Control Processor (AHCP)

***OVERVIEW:***

This bulletin involves a combination reprogramming of the HCP and the AHCP with the latest available software.

***MODELS:***

2017 (RU) Chrysler Pacifica (PHEV)

**NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA.**

**NOTE: This bulletin applies to vehicles built on or before **\*\*July 31, 2017 (MDH 0731XX)\*\*** and equipped with 3.6L V6 Hybrid Engine (Sales Code EH3) and Eflite SI-EVT Transmission (Sales Code DFQ).**

***SYMPTOM/CONDITION:***

Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation, a technician may find one or more of the following DTCs have been set:

- **\*\*P0A79-00 - Drive Motor B Inverter Performance.** The software has been updated to better address this DTC.
- P0A78-00 - Drive A Inverter Performance.\*\*
- U0415-00 - Implausible Data Received From ABS.
- P0A3F-00 - Drive Motor A Position Sensor 1 Circuit.
- P061B-00 - Internal Control Module Torque Calculation Performance.
- P26C3-00 - Internal Control Module Electronic Shifter Performance.

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

**NOTE: All UNSOLD vehicles will be updated with an upcoming recall.**

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. If any vehicle not on the VIN list exhibits the symptom/condition or DTC, perform the repair.

**REPAIR PROCEDURE:**

**NOTE: The **\*\*On Board Charging Module (OBCM),\*\* Powertrain Control Module (PCM) and Battery Pack Control module (BPCM) must be updated to the latest available software at the conclusion of this repair procedure. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the software.****

**NOTE: **\*\*Unsold vehicles can NOT be sold. Even if all of the open RRTs have been performed, unsold vehicles cannot be sold until the up-coming recall has been completed. \*\*****

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. **\*\*Does the HCP and AHCP control modules have the latest software already installed?**
  - Yes>>> This bulletin has been completed, use LOP (18-19-86-93) to close the active RRT. Proceed to [Step 4](#).
  - No>>> Proceed to [Step 2](#).

**NOTE: The HCP and AHCP are combined into one flash. The AHCP will flash right after the HCP.**

**NOTE: A vehicle scan report will be needed once ALL of the modules have been updated.**

2. Reprogram the HCP with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
3. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.
4. Verify the **\*\*OBCM\*\*** PCM and BPCM are programmed with the latest available software. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the software.
5. **\*\*Have all of the open RRTs been performed?**
  - Yes>>> Using wiTECH create a vehicle scan report and attach it to the work order.
  - No>>> Perform next open RRT.\*\*

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
**18-19-86-93	Processor, Hybrid Control (HCP/AHCP) - Inspect S/W Level Only (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
18-19-86-94	Processor, Hybrid Control (HCP/AHCP) - Inspect and Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.5 Hrs.**

**NOTE: The expected completion time for the flash download portion of this procedure is approximately 22 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.**

**FAILURE CODE:**

**The dealer must choose which failure code to use depending on if this is a Rapid Response Transmittal (RRT) or Service Bulletin.**

- If the customer’s concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C’s must be supplied.
- The failure code “RF” (Required Flash) can no longer be used on Service Bulletin flashes. The “RF” failure code can only be used on RRT.
- The “RF” failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RRT.

CC	Customer Concern
RF	Required Flash