



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-170

Date: May, 2016

TECHNICAL

Subject: Brake Pulsation and/or Vibration During Brake Apply

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2014	2016				

Involved Region or Country	North America and NA Export vehicles.
Additional Options (RPO)	BRAKE SYSTEM-HEAVY DUTY (RPO J55)
Condition	Some customers may comment on a pulsation and/or vibration when they apply the brakes.
Cause	This condition may be due to excessive lateral runout (LRO).

Correction



4519715



4519720



4519697



4519709

Check the lateral runout and replace the affected rotors with the new one piece design (1) **NOT** the old two piece design (2).

Important: The rotors **MUST** be replaced as a pair due to a design change.

Note: **DO NOT** replace all brake rotors unless you find the lateral runout out of spec for both the front and rear corners.

Service Procedure

Refer to *Brake Rotor Assembled Lateral Runout Correction and Front and Rear Brake Rotor Replacement-Both Sides* in SI.

Parts Information

Description	Part Number	Qty
ROTOR ASM-FRT BRK	23242229	2
ROTOR-RR BRK	23322785	2

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2420671	Front Brake Rotor Replacement - Both Sides	Use Published Labor Operation Time
2420761	Rear Brake Rotor Replacement - Both Sides	

Version	1
Modified	

